



AIG - LKK

**Esteem Performance Pte Ltd**  
**385 Sin Ming Drive, Vicom Vehicle**  
**Inspection Centre (575718)**

**Insurer Reference: SMH199P**  
**Repairer Reference: 031367**  
**Date calculated: 17/04/2020 10:05 AM**

**Full Report**  
**Registration: SLT8224X**  
**Printed: 17/04/2020 10:05 AM**

**Summary Information**

<b>Claim</b>		<b>Work Provider:</b>	AIG Asia Pacific Insurance Pte Ltd
Location:	Singapore (SG)	Currency:	SGD
Printed by:	Carmen SG	Date of Incident:	13/04/20
Claim Reference:	SMH199P	Hire Car Start:	
Estimated Repair Time:		Hire Car End:	
Actual Repair Days:			

**Vehicle Details**

<b>Vehicle</b>	
Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLT8224X
VIN number:	
Odometer:	

*Not Authored*  
*Repair B4 paint*  
*2 days*

**Model Specs**  
TWO COAT METALLIC

**Vehicle Condition**

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:


**Damage Areas**

**All**   
**Underbody**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	75.00
NO NUMBER	R + R L/F BUMPER MOUNTING		1.0	5.00
NO NUMBER	R + R R/F BUMPER MOUNTING		1.0	5.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			1.70	17.0
<b>Total of Labour</b>				<b>85.00</b>

## Paint

Code	Description - TWO COAT METALLIC	SYSTEM AZT	Time Basis 10 WU/h	
			WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		14.0	

### Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	67.90

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h		14.0	
Time Paint		0.90	9.0	45.00
Preparation Comp. Work Plastic		2.30	23.0	115.00
<b>Total</b>	<b>10 WU/h</b>			

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		67.90
Material-constant Plastic		16.20
<b>Total</b>		<b>84.10</b>

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	
				Price SGD	
1001	FOG LAMP LH	FOG LAMP LH		910.70	✓
0283	FRONT BUMPER	52119 47962		450.80	✓
0431	FRONT MANUFACT BADGE	75310 47060		87.10	✓
1000	FRT BMP CLIP	FRT BMP CLIP		40.00	✓
0317	L/F BUMPER BRACKET	52116 47050		107.20	✗
0318	R/F BUMPER BRACKET	52115 47050		107.20	✗
<b>Savings</b>				<b>0.00</b>	

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

<b>Subtotal</b>	<b>1,703.00</b>
<b>Subtotal Discount(+30.00%)</b>	<b>-510.90</b>
<b>Total</b>	<b>1,192.10</b>

### Extras

Code	Description	Price SGD
1002	TO CHECK WIRING TO CHECK WIRING	50.00*
	<b>Total Extras</b>	<b>50.00</b>

201

### Final Calculation

	SGD	SGD
<b>Parts</b>	1,703.00	
Total Discount(+30.00%)	-510.90	
<b>Total Parts</b>		<b>1,192.10</b>
<b>Labour Time Base 10 WU/h</b>		
Total 17.0 WU X 50.00 SGD/h	85.00	
<b>Total of Labour</b>		<b>85.00</b>
<b>Total Of Extras</b>		<b>50.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 23.0 WU X 50.00 SGD/h	115.00	
Material Cost	84.10	
<b>Total Paint Including Material</b>		<b>199.10</b>
<b>Repair Cost Excludes GST</b>		<b>1,526.20</b>
GST (+7.0%)		<b>106.83</b>
<b>Repair Cost Included GST</b>		<b>1,633.03</b>

### Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.