



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002998  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE  
SINGAPORE 189556

INV Date 28/05/2020  
Reference NS/INC20005260/T1yf3n2  
Code INC4



### PROFESSIONAL SERVICE FEE

Vehicle No. SH 7747R  
Insured Veh. YQ 2153T  
Claim No. MT/1092676-001  
Policy No. 5114607176  
Accident Date 15/04/2020  
Inspection Date 16/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

*HYN*




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005260/T1yf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 28-05-2020	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 2153T	Veh. Inspected	SH 7747R	
Policy No.	5114607176	Coverage (\$)	0.00	
Claim No.	MT/1092676-001	Excess (\$)	0.00	
Assign From		Assign Date	16/04/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203564066	Colour	BLUE	
Odometer	379483	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	6 mm	
L/H Front Tyre	195/65 R15	DAVANTI	6 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	6 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	6 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	15/04/2020	Inspection Date	16/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR: <b>2 Working Days</b>			



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7747R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	DEFORMED	490.50	490.50
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER-RH	DEFORMED	82.30	82.30
1	HEADLAMP-RH	CUT	3,455.00	3,455.00
	LESS 25% DISCOUNT		-1,012.45	-1,012.45
			3,037.35	3,037.35
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		350.00	320.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	WIRING CHARGE.		50.00	30.00
			700.00	550.00
	<b>GRAND TOTAL</b>		<b>3,737.35</b>	<b>3,587.35</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,850.00</b>

Report Ref No. NS/INC20005260/T1yf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 7747R

INSPECTION





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**PHOTOGRAPHS FOR VEHICLE NO. SH 7747R**

**RE-INSPECTION**

