

**REPAIR ESTIMATE\***

VEHICLE NO : SH 7747R

DATE: 16. Apr. 2020

MAKE : TOYOTA

MODEL : PRIUS

DOA: 15. Apr. 2020

**NTUC**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover			\$490.50
10	Front Bumper Clips		\$2.20	\$22.00
1	Front Bumper Side Retainer – RH			\$82.30
1	Headlamp – RH			\$3,455.00
<b>SUB TOTAL</b>				<b>\$4,049.80</b>
<b>LESS 25%</b>				<b>\$1,012.45</b>
<b>DISCOUNTED TOTAL</b>				<b>\$3,037.35</b>
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<b>Labour Charge</b>				
1	Panel Beating		320	\$350.00
1	Spray Painting Charge		200	\$300.00
1	Wiring Charge		30	\$50.00
<b>TOTAL LABOUR</b>				<b>\$700.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$3,737.35</b>
<p>Larry Ng</p> <p>1/5 \$ 2850</p>				02 days
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfu 97495744  
02 days. WP 16/4/200340  
Lumpsum  
Recovery of repair  
src lkkauto.com  
tanfu@lkkauto.com