

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd
Date: 17/4/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLR4250G
 CHASSIS NO : GP71044206
 MAKE / MODEL : Honda Shuttle 1.5 Hybrid
 DATE OF ACCIDENT : 03/04/2020
 YOUR INSURED VEHICLE NUMBER: SFK9218B
 MILEAGE : 173104 Km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/L fender X R	1PC	\$ 2,000.00	\$ 2,000.00 X R
2	Rear bumper X R	1PC	\$ 1,500.00	\$ 1,500.00 X R
		Total	\$	3,500.00
		Less 20%	\$	700.00
			\$	2,800.00

	<u>SPECIAL NETT</u>	
1	Bumper clips X Svc	1 SET \$ 200.00 X
	Special Nett Total S\$:	\$ 200.00

	<u>LABOUR CHARGES</u>	
1	To labour charge for removing R/L door, R/L fender and rear bumper to facilitate repairs and replacement of damaged parts.	\$ 750.00 300 350
2	To respray rear bumper, R/L fender and R/L door	\$ 900.00 600
3	Transfer door mechanism to facilitate repairs and replacement of parts X	\$ 120.00
	LABOUR TOTAL S\$:	\$ 1,770.00 950.
	TOTAL S\$:	\$ 4,770.00
	7% GST	\$ 333.90
	GRAND TOTAL S\$:	\$ 5,103.90

Repair dly - 2 days

P/P

Lts P/P

\$ 950

After paint photo.

Sun Pm (Lkl)

17/04/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to information
- Third party survey is on "No Prejudice" basis
- No illegal modifications
- Supplementary items are surveyed and is subject to final approval from Insurance Company

Acknowledged by:

Signature:

Date: