

Registration No. YN 3693K

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Windscreen	1				
1.2	Windscreen Moulding	1				
1.3	Windscreen Sealant	1				
1.4	Windscreen Primer	1				
1.5	Front Panel	1				
1.6	Radiator Grille	1				
1.7	Front Bumper	1				
1.8	Front Bumper Support	1				
1.9	Front Number Plate	1				
1.10	Front Panel Sticker	1				
	LABOUR DESCRIPTION					
1	SCOPE OF REPAIRS					
1.1	Remove & replace shuttered wind screen					4
1.2	Replace wind screen moulding					1
1.3	Water seepage for wind screen					1
1.4	Remove & replace front dented panel					4
1.5	Remove & replace dislodged radiator grill					1
1.6	Remove & replace front dented bumper					2
1.7	Remove & replace front dented bumper support					2
1.8	Remove & replace front dented number plate					0.5
1.9	Replace front panel sticker					1
1.10	Putty & spray paint front panel , radiator grill & front bumper					5

3	COLLECTION & DELIVERY					
3.1	Collection From Station - Workshop (SOR 10)	1				
3.2	Delivery From Workshop - Station (SOR 9)	1				
4	ADDITIONAL SERVICES					
4.1	Admin Support					0
		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				21.5