

Registration No.YN 3945J

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Cabin mounting bar assy	1				
1.2	Power steering pump	1				
1.3	Power steering shaft	1				
1.4	Front bumper	1				
1.5	Front bumper support	2				
1.6	Fog lamp LH & RH	2				
1.7	Signal lamp LH & RH	2				
1.8	Head lamp LH & RH	1				
1.9	Radiator grille	1				
1.10	Wind screen	1				
1.11	Wind screen moulding	1				
1.12	Wind screen sealant	1				
1.13	Wind screen preimer	1				
1.14	L/H mud flap	1				
1.15	L/H door garnish	1				
1.16	R/H step board	1				
1.17	Steel rim	1				
1.18	L/H dented door shell	1				
1.19	L/H door signal lamp	1				
1.20	Air bag & sensor	1				
1.21	Front number plate	1				
1.22	Panel sticker	1				
1.23	Gear box	1				
1.24	Gear box mountings	3				

1.25	Engine mountings	4				
	LABOUR DESCRIPTION					
1	SCOPE OF REPAIRS					
1.1	Remove & replace cabin dented mounting bar					5
1.2	Remove & replace power sterling unit					2
1.3	Remove & replace dented power sterling shaft					2
1.4	Remove & replace front dented bumper					2
1.5	Remove & replace front dented bumper support					2
1.6	Remove & replace both dislodged fog lamp					1
1.7	Remove & replace both signal lamp					1
1.8	Remove & replace both head lamp					2
1.9	Replace dislodged radiator grille					1
1.10	Remove & replace shuttered wind screen					3
1.11	Replace wind screen moulding					1
1.12	Water seepage for wind screen					1
1.13	Remove & replace L/H mud flap					1
1.14	Replace L/H door garnish					0.5
1.15	Remove & replace front R/H step board					1
1.16	Remove & replace front L/H dented door shell					2
1.17	Transfer front L/H door inner panel, door handle & accessories to new door shell					4
1.18	Replace L/H door signal lamp					0.5
1.19	Remove & replace driver air bag & sensor					0
1.20	Remove & replace front dented number plate					0.5
1.21	Repair & align misalign dash board					3
1.22	Repair & align tilted cabin					20
1.23	Remove & replace front panel sticker					1
1.24	Panel beat front dented panel					3
1.25	Remove & replace gear box					5
1.26	Remove & replace gear box mounting					2
1.27	Remove & replace engine mounting					2
1.28	Putty & spray whole complete front cabin					20

1.29	Wiring for all replacement lighting					4
3	COLLECTION & DELIVERY					
3.1	Collection From Station - Workshop (SOR 9)	1				
3.2	Delivery From Workshop - Station (SOR 9)	1				
4	ADDITIONAL SERVICES					
4.1	Admin Support					0
2.1						0
COSTING		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				92.5