

22/03/2002

ASS. REC. BY:

REF: CS/EG120005266/ Evf3

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Pauline Soh

of Erya

Date/Time: 17.4.20 8.57a.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

PA 92482

Insured:

YN 5515D

at Workshop m/s

my car consultant

Tel:

88662832

of

53 ubi Ave 1 Pagar ubi

Policy No:

Claim No:

CD MCG 20000603

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14. Apr. 2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

nop

H.O.D. Endorsement:

Date/Time:

17.4.20 10.30a.m

Person Contacted:

Hui Qin

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YN 92482 - X

YN 5515D - MA/FCL20005266/P Dof - 14/04/2020

20/4/20

Send preli revised via merimen



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

Vehicle:

Make / Model:

Chassis:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/4/2020

PA9248Z

NISSAN URVAN

JN1TG4E25Z0786017

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR TAILGATE / DD	1	\$ 1,926.20	\$ 1,926.20
2	REAR TAILGATE LOCK X NAI		\$ 354.60	\$ 354.60
3	REAR TAILGATE LOCK CATCH X NAI		\$ 51.70	\$ 51.70
4	RH REAR TAILLAMP / DR		\$ 230.90	\$ 230.90
5	REAR TAILLAMP LOWER BRACKET X NAI		\$ 35.60	\$ 35.60
6	REAR BUMPER / DR		\$ 760.60	\$ 760.60
7	REAR BUMPER SIDE RETAINER RH / DR		\$ 28.10	\$ 28.10
8	REAR BUMPER STEP PANEL X NAI		\$ 179.60	\$ 179.60
9	RH REAR FENDER X R		\$ 4,010.20	\$ 4,010.20
			10	\$ 7,577.50
			Less 25%	\$ 1,894.38
			Total	\$ 5,683.13
S/Nett items:				
1	REAR REVERSE SENSOR X NAI	1 SET	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP / MC	1 SET	\$ 80.00	\$ 80.00
3	REAR TAILGATE 70KM/H STICKER / MC	1	\$ 18.00	\$ 18.00
4	REAR BUMPER STEP GARNISH CLIPS X NAI	2	\$ 8.50	\$ 17.00
5	REAR WINDSCREEN GLASS SEALANT / MC	1	\$ 60.00	\$ 60.00
6	RH REAR FENDER GLASS SEALANT X NAI	1	\$ 60.00	\$ 60.00
7	MISCELLANEOUS X NAI		\$ 200.00	\$ 200.00
				\$ 685.00
Labour to:				
40	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00
41	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 120.00	\$ 120.00
	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 120.00	\$ 120.00
	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	\$ 150.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 180.00	\$ 180.00
	REMOVE AND REFIX RH REAR GLASS	1	\$ 180.00	\$ 180.00
43	TO RESPRAY UNDERCOATING	1	\$ 200.00	\$ 200.00
44	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
45	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
46	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
				\$ 3,750.00
Steve (LKR) WML AL			Parts Replacement Amount	\$ 6,368.13
17/4/20, 11:30am LIS, 5 dgs			Total Amount for Labour	\$ 3,750.00
Ry AL Sj			Total Amount	\$ 10,118.13

11,254.75

632

2817.20

-19%

2535.48

X

30

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X