a fifther p	20003267/Kf ASSIGNMENT
From:	
Estimated Cost:	Veh No: SUK 1/7/14 Yr Regn: 01, 17 Type: McCarl M. Cycle / Bus / Van / Lower / Type: McCarl M. Cycle / Bus / Van / Lower / Type: War / M. Cycle / Bus / Wa
OD VIP WS / TP RES / OD RES / EVA / INV / MV	- Corry TaxI / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
	Make: Toy Print cc 1798
at Workshop m/s Esteen	Colour M. P. White AC: Insured / Std / NI / NA
Insured:	Sp.Reading 168170 T/Radlo: Insured / Std / NI / NA
	Eng/No:
Policy No.	CNO: JTD KB3 FU 9035\$1044
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/Rim / STD A/Rim or
Visit in the second second	Tyre Size: F: P5/15015
(Policy Condition)	Tyre Size: F: P5/65R15
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal, or Market Value:	Eront Book
DAC Accident Rport: Consistent? : Yes or No	R/Rail & Rear
GIA / PR Seen: Consistent? : Yes or No	Mm R/Bal. 3 mm
st. Repairs: 1-2 days Res.: Yes or No	DOA 12/2/2
um Sum: 1. 13.1 % 3 Val.: Yes or No	
A / REV / REP. / 24 HRS	Survey held at
. Vahida IV (OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
ete:Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
/	
Time, File Pass to? : Prell. Report	Pays Of Repair:
: Final Report	
/Time, File Return to?	Survey No. of Trip: Survey Fee:
Add Fee:	: Site Insp (\$ ) _s+Rs_si
*	Intended (P
port Format :	Toch Inva (S
	Tech mys (3
np Sum / I.B.I: (S	Weekend (\$

Operan Spronen



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Repair Estimates	SLK 1171 H	
Parts (a) Cost / List Price Items	\$ 1,744.40	Not Swithorks
Plus/Less25%_	\$ 436.10	
Total of Cost / List	\$ 1,308.30	LKK Auto Consultants hence notify the Repairer of the following:  To resurvey before/after spray cointing
(b) Nett Price Items		To display damaged parties alway resurvey Parts prices are subject to confirm an on.
Less		Third party survey is on a "Without Prejudice" basis     No illegal modification(s, s, allowed.
Total of Nett Item		<ul> <li>Suppler entiry iten (c, must be resurveyed and is subject to final approval from Insurance Company</li> </ul>
(c) Special Nett Items	\$ 200.00	Acknowledged by Repairer Signature:
Total Parts Cost	\$ 1,508.30	Date:
_abour	\$ 970.00	
Total	\$ 2,478.30	

The above total will be subjected to 7% G.S.T.

Nam	e of Surveyor	:	Kennery	
	pany	:	6KK	
	ey conducted on	:	11/5/20 at_	11.50cm
Ren	narks By Surveyor			
(a)	The repair of this vehicle is auth	ziźed .	/ is not authorized until further notice.	
(b)	Recommended Days of Repair	:	1-2 day(s)	
(c)	Resurvey	:	Required / Not Bequired	
(d)	Excess	:\$_		
(e)	Signature of surveyor	:	Le Dat	te:



## ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

S	pa	re	Par	rts
---	----	----	-----	-----

Vehicle No. :	SLK 1171 H	Submit By	:	Carmen Lim
Make & Model:	TOYOTA PRIUS	Year Manufacture		2017 Jan
Chassis No :	JTDKB3FU903541044	Engine No.		
5 A SURFERENCIA DE 1997 OPT TOUR DE 1997 DE 19	Mile Control	Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sin	1	\$200.00	S.N	X
2	Rear bumper	N	1	\$497.50		<b>×</b>
3	Rear bumper clip	nn	10	\$40.00		×
4	Rear bumper side retainer LH	Sm	1	\$112.70		X
5	Rear bumper side retainer RH	14	1	\$112.70		X
6	Rear bumper reinforcement		1	\$398.90		7
7	Rear bumper lower garnish centre	Se Se	1	\$582.60	7	X
8		1			THE STATE OF THE S	
9						ids.
10						**
11						
12				11/2	16.1	1
13			in the same			
14						
15						j. j.
16	A Section 1					
17						
18						
19		A	Liji			
20	No.		No.			
21		15	- 1			
22		Market .				
23						8-900-0

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N



### ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

La	h	0	u	r

Vehicle No.	:	SLK 1171 H	Submit By	:_	Carmen Lim	
Make & Model	:	TOYOTA PRIUS	Year of Manufacture		2017 Jan	7

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
ja ja	REPAIR AREA. (REAR BUMPER)	\$400.00	7
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER)	\$400.00	2201
3	To check wiring	\$50.00	X
4	To remove & refit reverse sensor	\$120.00	?
	The state of the s		
		No. of the last	
	N. C.		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	Three of the artificing of the report of	manufacture and the second	
10.25 3 5 5 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6	ACCIDENT STATEMENT	A Committee of the second	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )
Date Of Report	23/03/2020 14:20		
Date Of Accident	12/02/2020 20:40		
Exact Location Of Accident	ALONG JURONG WEST ST 64		
Country/State of Loss	SINGAPORE		
The second of the second	DETAILS OF OWN VEHICLE	Sound State of	23800
Vehicle Registration Number	SLK1171H		
Insured/Policyholder			
Name Of Registered Owner	GRAB RENTALS PTE LTD		
Co Reg No	2XXXXX200G		
Email Address	NOEMAIL		
Mobile Phone No			
Alternative Phone No	OFFICE-31388644		
Vehicle Particulars			
Manufacturer	TOYOTA		

PRIUS-1.8 HYBRID CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

Model

Are you claiming under your own insurance policy

for repair to your vehicle?

1.0

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy YES
Policy Number 29141713

Cover Note Number

Driver

 Name of Driver
 TEH TECK HING

 NRIC No
 SXXXX037D

 Date Of Birth
 21/10/1964

 Occupation
 OUTDOOR

 Date Of Driving Pass
 14/08/1992

Driving Experience 27 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91852265

Fax Number Contact Number

EMail Address NOEMAIL

Page 1 of 15

Address

BLK 540 WOODLANDS DRIVE 16 #02-83

Postcode

730540

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - LESSEE

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

**Details of Police Action** 

NO

Was the accident reported to the police? If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

ON 12/02/2020 AT AROUND 8:40PM, I STOPPED MY CAR ON LANE 2 OF JURONG WEST ST 64 OUTSIDE JURONG LIBRARY TOWARDS GEK POH. SUDDENLY VEHICLE B DROVE UP FROM BEHIND AND COLLIDED INTO MY STATIONARY CAR. MY CAR SUSTAINED REAR DAMAGES. NO ONE WAS INJURED.

## Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGN8804M

Vehicle Make/Model/Colour

VEH B

**Details Of Properties** Vehicle Category

PRIVATE CAR

Name of Driver

MOHD NOR BIN SAMSUDIN

NRIC/Passport Number

SXXXX891A

Contact Number

82924473

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 15