

ASS. REC. BY:

REF:

20005267/kf

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1-2 days

Res.: Yes or No

Lum Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK 11714 Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius c.c. 1798

Colour:

M. P. White A/C: Insured / Std / NI / NA

Sp. Reading:

188170 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU903541044

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

3 mm

L/Bal.

4 mm

L/Bal.

3 mm

D.O.A.

12/2/20

D.O.I.

11/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/5 @ 320h Can firm

Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Firms

) Others

TOTAL

ort Format :

p Sum / I.B.I. (\$

REF: Tm1/

ASSIGNMENT



ESTEEM PERFORMANCE PTE LTD

 Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

 Vehicle No. :
 Make & Model :
 Chassis No :

SLK 1171 H

TOYOTA PRIUS

JTDKB3FU903541044


 Submit By :
 Year Manufacture :
 Engine No :
 Cost / List

Carmen Lim

2017 Jan

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		X
3	Rear bumper clip	10	\$40.00		X
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90	repair	7
7	Rear bumper lower garnish centre	1	\$582.60		X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					
47					
48					
49					
50					

If any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.



Submit By : Carmen Lim
Year of Manufacture : 2017 Jan

g No. 200005485N / GST No. 20-0005485-N