

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005272/QPA3Q2
Date: 29/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900089389
Claimant Vehicle No :	SLH4305K	Insured Vehicle No :	SMK6929U
Date of Loss:	15/04/2020	Nature of Claim:	TP
		Claim No:	9738995158SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4305K	Engine No:	LEB4264168
Make & Model:	HYUNDAI ACCENT, 1.5 GLS (A)	Chassis No:	GP71044191
Reg. Date:	02/11/2016 (Man. Year: 2016)	Odometer:	262033 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,584.80	2,501.76	1,083.04	30.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,520.00	620.00	28.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,724.80	4,021.76	1,703.04	29.75
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,724.80	3,200.00	2,524.80	44.10
+ GST 7.00/7.00% (S\$)	400.74	224.00	176.74	44.10
Nett Amount (S\$)	6,125.54	3,424.00	2,701.54	44.10
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,676.00		
Global Sum Settlement (S\$)		3,670.00		

INSPECTION

Date of Assignment:	17/04/2020		
Date Inspected:	17/04/2020	Inspected At:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-35/36 Carros Centre Singapore 737569
Estimated Period of Repair:	4.0 days		

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,200.00 FL	
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*110.00 FL	
3	1		*REAR TAILGATE WEATHERSTRIP	Cut	255.00 FL	*255.00 FL	
4	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL	
5	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL	
6	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	86.30 FL	*86.30 FL	
7	1		*REAR BUMPER	Cut	1,350.00 FL	*1,100.00 FL	
8	1		*END PANEL (NPA)	Repair	0.00 FL	*- FL	
9	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS	
10	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS	
11	1		*SET END PANEL TO GARNISH CLIPS	Serviceable	80.00 FS	*- FS	
					Sub Total (\$\$)	4,366.00	3,069.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	781.20	567.94
					Total Parts (\$\$)	3,584.80	2,501.76

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REAR TAILGATE,REAR BUMPER,END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPARE TRYE PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS	New	900.00	700.00
2	TO RESPRAY REAR BUMPER,END PANEL,SPARE TYRE PANEL AND TAILGATE	New	900.00	600.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
5	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	40.00
Gross Labour Cost (S\$)			2,140.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >