

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **GBE4304Y**
 Model: **Toyota Hiace**
 Chassis No:
 Year of manufacturing:

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Item			
	Rear bumper / <i>DD</i>	1		685.60
	Rear bumper retainer RH / <i>BR</i>	1		92.60
	Rear bumper retainer LH / <i>BR</i>	1		92.60
	Rear bumper bracket / <i>DT</i>	1 3		220.00
	Rear corner panel RH ?	1		158.70
	Tail lamp RH / <i>BR</i>	1		486.70
	Tail lamp LH X	1		486.70
	Tail gate / <i>DD</i>	1		2150.70
	Tail gate lock / <i>DT</i>	1		225.30
	Tail gate lock catch X	1		75.50
	Tail gate key lock X	1		105.20
	Tail gate lock handle X	1		142.80
	Tail gate license lamp garnish X	1		155.20
	Tail gate license lamp X	2		79.60
	Tail gate logo emblem / <i>MC</i>	1		79.60
	Tail gate rubber beading / <i>CR4</i>	1		226.80
	Tail gate inner trim X	1		338.40
	Tail gate damper RH X	1		152.50
	Tail gate damper LH X	1		152.50
	Tail gate hinge RH X	1		135.30
	Tail gate hinge LH X	1		135.30
	Tail gate windscreen X	1		1120.00
	Tail gate windscreen moulding / <i>MC</i>	1		223.60
	End panel / <i>DD</i>	1		865.50
	Rear floor panel X <i>R</i>	1		1752.30
				10339.00
Special Nett Items				
	Reverse sensor set / <i>SM</i>	1		250.00 <i>200</i>
	Reverse camera X	1		350.00
	Rear number plate X	1		45.00
	Rear bumper clip set / <i>MC</i>	1		50.00 <i>30</i>
	Tail gate inner trim clip set X	1		50.00
	Tail lamp clip set X	1		30.00
	Tail gate sticker - Toyota Hiace / <i>MC</i>	1		100.00 <i>50</i>

Tail gate sticker - 70km/h / MK	1	50.00	40
Tail gate windscreen sealant / MK	1	50.00	
Tail gate windscreen inner seal / MK	1	30.00	20
End panel sealant / MK	1	50.00	30
Rear floor panel sealant X	1	50.00	
		<u>1105.00</u>	

Labour & Miscellaneous Charge

To R&R rear bumper reverse sensor	80.00	30
To check wiring and lighting system	80.00	30
To supply under-coating / putty on part replaced	80.00	30
To perform anti rust treatment on affected areas	60.00	30
To R&R rear windscreen	200.00	120
To R&R tail gate mechanism	200.00	80
To R&R rear trims and garnish assy	180.00	X
To repair, replace and realign damaged areas	1000.00	800
To spray painting on affected areas	900.00	400 500
To perform water seepage test after repair	150.00	30
Sundries	50.00	30
	<u>2980.00</u>	

List Items Subtotal
Special Nett Items Subtotal
Labour Items Subtotal
Total

Steve (LKK)
8322 8813
Steve.chm@lkkauto.com

WML MK
20/4/79, 2.00 pm
L/S
My MK sig
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: