



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

DATE : 17-Apr-20

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : YM9530M
 MODEL : ISUZU FV
 DATE OF ACCIDENT : 7/4/2020
 TIME OF ACCIDENT : 1635H

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP (LH) / OR	1	\$ 360.00	\$ 720.00
2	REAR REINFORCEMENT / DD	1	\$ 2,860.00	\$ 2,860.00

TOTAL PRICE \$ 3,580.00
 LESS 15% \$ 537.00
 SUB TOTAL PRICE \$ 3,043.00

CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL GATE '60KM STICKER / MC	1	\$ 30.00	\$ 30.00
2	TAIL GATE '45PAX' STICKER, X	1	\$ 30.00	\$ 30.00
3	TAILGATE WOODEN (SPECIAL TYPE) / DT	1	\$ 2,100.00	\$ 2,100.00
4	TAILGATE HINGE (SPECIAL TYPE) / DT	4	\$ 135.00	\$ 540.00
5	REAR STEP BRACKET (SPECIAL TYPE) / DD	1	\$ 900.00	\$ 900.00
6	REAR CARGO BED REAR FRAME (SPECIAL TYPE) X R	1	\$ 1,350.00	\$ 1,350.00
7	REAR CARGO BED REAR END BEAM (WOODEN) X / OR	1	\$ 1,800.00	\$ 1,800.00
8	REAR CARGO BED BOTTOM BEAMS (SPECIAL TYPE) X	13	\$ 1,200.00	\$ 15,600.00
9	CARGO BED CHASSIS MEMBER (WOODEN) X	2	\$ 6,300.00	\$ 12,600.00
10	CARGO BED REAR CROSS MEMBER (WOODEN) X R	1	\$ 1,350.00	\$ 1,350.00
11	CARGO BED FLAP (WOODEN) X	7	\$ 1,650.00	\$ 11,550.00
12	CARGO BED U CLIP X	6	\$ 187.50	\$ 1,125.00
13	TAIL LAMP BACK SUPPORT BRACKET (SPECIAL TYPE) X	2	\$ 135.00	\$ 270.00

TOTAL \$ 49,245.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 1,800.00	1990
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,800.00	590


TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : YM9530M
 MODEL : ISUZU FV
 DATE OF ACCIDENT : 7/4/2020
 TIME OF ACCIDENT : 1635H

3	BULB CHECKING, WIRING	\$ 180.00	30
4	REAR CHASSIS ALIGNMENT	\$ 250.00	X
5	TO REMOVE / REFIX CARGO BED	\$ 2,800.00	X
6	REMOVE AND REFIX REAR CANOPY	\$ 650.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL 7,660.00

TOTAL PARTS COST : \$ 52,288.00
 TOTAL LABOUR COST : \$ 7,660.00
 TOTAL REPAIR COST : \$ 59,948.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.



Steve (LKK)
 8322 8813

wil mil
 17/4/20, 3.90pm
 L/S
 By AL SJ
 7 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: