



# MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934  
HP: 98888885

- Parts prices are subject to commission
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimation

Ry (Hew)  
17/4/20

Date:

15/4/2020

Vehicle:

SJE7312J

Make / Model:

HONDA FIT

Chassis:

GE6-1037804

| No. | Description                                         | Unit | Unit Price  | Amount      |
|-----|-----------------------------------------------------|------|-------------|-------------|
|     | Parts Replacement:                                  |      |             |             |
| 1   | REAR TAILGATE / <i>DD</i>                           | 1    | \$ 1,662.70 | \$ 1,662.70 |
| 2   | REAR TAILGATE LOCK / <i>BT</i>                      | 1    | \$ 290.10   | \$ 290.10   |
| 3   | REAR TAILGATE LOCK CATCH X                          | 1    | \$ 48.60    | \$ 48.60    |
| 4   | REAR TAILGATE OUTER GARNISH ? / <i>DR</i>           | 1    | \$ 325.20   | \$ 325.20   |
| 5   | REAR TAILGATE OUTER HANDLER X                       | 1    | \$ 139.30   | \$ 139.30   |
| 6   | REAR TAILGATE NUMBER PLATE LAMP X                   | 2    | \$ 68.40    | \$ 136.80   |
| 7   | REAR TAILGATE OUTER GARNISH LOGO ? / <i>MC</i>      | 1    | \$ 70.00    | \$ 70.00    |
| 8   | REAR TAILGATE EMBLEM FIT / <i>MC</i>                | 1    | \$ 54.00    | \$ 54.00    |
| 9   | REAR TAILGATE INNER TRIM BOARD / <i>CR4</i>         | 1    | \$ 774.60   | \$ 774.60   |
| 10  | REAR TAILGATE 3RD BRAKE LIGHT X                     | 1    | \$ 180.60   | \$ 180.60   |
| 11  | REAR TAILGATE LOCK CABLE / <i>TN</i>                | 1    | \$ 89.10    | \$ 89.10    |
| 12  | REAR TAILGATE SHOCK ABSORBER LH X                   | 1    | \$ 321.50   | \$ 321.50   |
| 13  | REAR TAILGATE SHOCK ABSORBER RH X                   | 1    | \$ 321.50   | \$ 321.50   |
| 14  | REAR TAILGATE HING LH / <i>BT</i>                   | 1    | \$ 92.50    | \$ 92.50    |
| 15  | REAR TAILGATE HING RH X                             | 1    | \$ 92.50    | \$ 92.50    |
| 16  | REAR TAILGATE RUBBER STOPPER LH X                   | 1    | \$ 14.20    | \$ 14.20    |
| 17  | REAR TAILGATE RUBBER STOPPER RH X                   | 1    | \$ 14.20    | \$ 14.20    |
| 18  | REAR TAILGATE WIPER MOTOR X                         | 1    | \$ 448.70   | \$ 448.70   |
| 19  | REAR TAILGATE WIPER MOTOR ARM X                     | 1    | \$ 112.30   | \$ 112.30   |
| 20  | REAR TAILGATE WIPER BLADE X                         | 1    | \$ 36.40    | \$ 36.40    |
| 21  | REAR TAILGATE WIRE HARNESS X                        | 1    | \$ 445.70   | \$ 445.70   |
| 22  | REAR TAILGATE WINDSCREEN GLASS / <i>DR</i>          | 1    | \$ 1,309.10 | \$ 1,309.10 |
| 23  | REAR TAILGATE WINDSCREEN GLASS MOULDING / <i>MC</i> | 1    | \$ 135.30   | \$ 135.30   |
| 24  | REAR BOOT WEATHER STRIPE / <i>CR4</i>               | 1    | \$ 203.60   | \$ 203.60   |
| 25  | REAR BUMPER / <i>DD</i>                             | 1    | \$ 890.80   | \$ 890.80   |
| 26  | REAR BUMPER SIDE RETAINER LH / <i>DR</i>            | 1    | \$ 80.30    | \$ 80.30    |
| 27  | REAR BUMPER SIDE RETAINER RH / <i>DR</i>            | 1    | \$ 80.30    | \$ 80.30    |
| 28  | REAR END PANEL / <i>DR</i>                          | 1    | \$ 796.60   | \$ 796.60   |
| 29  | REAR END PANEL TOP GARNISH ? / <i>CR4</i>           | 1    | \$ 260.80   | \$ 260.80   |
| 30  | REAR SPARE TYRE COMPARTMENT X / <i>DR</i>           | 1    | \$ 1,237.73 | \$ 1,237.73 |
| 31  | REAR SPARE TYRE TOP COVER BOARD ? / <i>TN</i>       | 1    | \$ 292.30   | \$ 292.30   |
| 32  | REAR SPARE TYER SPONGE ? / <i>CR4</i>               | 1    | \$ 221.40   | \$ 221.40   |
| 33  | REAR FLOOR PANEL RH X                               | 1    | \$ 226.70   | \$ 226.70   |
| 34  | REAR FLOOR PANEL LH X                               | 1    | \$ 226.70   | \$ 226.70   |
| 35  | REAR TAILLAMP LH / <i>DR</i>                        | 1    | \$ 516.20   | \$ 516.20   |
| 36  | REAR TAILLAMP LOWER BRACKET LH ? X                  | 1    | \$ 65.30    | \$ 65.30    |
| 37  | REAR TAILLAMP INNER PANEL LH ? / <i>BT</i>          | 1    | \$ 178.30   | \$ 178.30   |
| 38  | REAR TAILLAMP CLIPS LH / <i>MC</i>                  | 2    | \$ 6.50     | \$ 13.00    |

5.90

SJE7312J

|                                                         |                                                |       |                          |              |       |
|---------------------------------------------------------|------------------------------------------------|-------|--------------------------|--------------|-------|
| 39                                                      | REAR TAILLAMP RH ? / DR                        | 1     | \$ 516.20                | \$ 516.20    |       |
| 40                                                      | REAR TAILLAMP LOWER BRACKET RH ? X             | 1     | \$ 65.30                 | \$ 65.30     |       |
| 41                                                      | REAR TAILLAMP INNER PANEL RH X                 | 1     | \$ 178.30                | \$ 178.30    |       |
| 42                                                      | REAR TAILLAMP CLIPS RH ? / MC                  | 2     | \$ 6.50                  | \$ 13.00     | 5.00  |
| 43                                                      | LH REAR FENDER / DR                            | 1     | \$ 752.40                | \$ 752.40    |       |
| 44                                                      | LH REAR FENDER AIR VENT ? X                    | 1     | \$ 62.40                 | \$ 62.40     |       |
| 45                                                      | LH REAR FENDER INNER COWLING ? / MC            | 1     | \$ 91.50                 | \$ 91.50     |       |
| 46                                                      | LH REAR FENDER INNER TRIM BOARD BOTTOM ? / CRH | 1     | \$ 643.80                | \$ 643.80    |       |
| 47                                                      | LH REAR FENDER INNER TRIM BOARD TOP ? / DR     | 1     | \$ 228.60                | \$ 228.60    |       |
| 48                                                      | RH REAR FENDER X R                             | 1     | \$ 752.40                | \$ 752.40    |       |
| 49                                                      | RH REAR FENDER AIR VENT X                      | 1     | \$ 62.40                 | \$ 62.40     |       |
| 50                                                      | RH REAR FENDER INNER COWLING X                 | 1     | \$ 91.50                 | \$ 91.50     |       |
| 51                                                      | RH REAR FENDER INNER TRIM BOARD BOTTOM X       | 1     | \$ 643.80                | \$ 643.80    |       |
| 52                                                      | RH REAR FENDER INNER TRIM BOARD TOP X          | 1     | \$ 228.60                | \$ 228.60    |       |
|                                                         |                                                |       |                          | \$ 16,735.13 |       |
|                                                         |                                                |       | Less 20%                 | \$ 3,347.03  |       |
|                                                         |                                                |       | Total                    | \$ 13,388.10 |       |
|                                                         | S/Nett items:                                  |       |                          |              |       |
| 1                                                       | REAR REVERSE SENSOR / SLA                      | 1 SET | \$ 250.00                | \$ 250.00    | 200   |
| 2                                                       | REAR BUMPER CLIP / MC                          | 1 SET | \$ 80.00                 | \$ 80.00     | 30    |
| 3                                                       | REAR END PANEL GARNISH CLIP / MC               | 1 SET | \$ 30.00                 | \$ 30.00     | 20    |
| 4                                                       | FLOOR PANEL SEALANT X                          | 1     | \$ 50.00                 | \$ 50.00     |       |
| 5                                                       | END PANEL SEALANT / MC                         | 1     | \$ 50.00                 | \$ 50.00     | 30    |
| 6                                                       | LH REAR FENDER INNER TRIM BOARD CLIPS / MC     | 1 SET | \$ 80.00                 | \$ 80.00     | 20    |
| 7                                                       | RH REAR FENDER INNER TRIM BOARD CLIPS X        | 1 SET | \$ 80.00                 | \$ 80.00     |       |
| 8                                                       | REAR TAILGATE INNER TRIM BOARD CLIPS / MC      | 1 SET | \$ 80.00                 | \$ 80.00     | 20    |
| 9                                                       | REAR WINDSCREEN GLASS SEALANT / MC             | 1     | \$ 60.00                 | \$ 60.00     | ✓     |
| 10                                                      | REAR REVERSE CAMERA X                          | 1     | \$ 300.00                | \$ 300.00    |       |
| 11                                                      | MISCELLANEOUS X                                |       | \$ 300.00                | \$ 300.00    |       |
|                                                         |                                                |       |                          | \$ 1,360.00  |       |
|                                                         | Labour to:                                     |       |                          |              |       |
| 1                                                       | TO CHECK ELECTRICAL WIRING                     | 1     | \$ 50.00                 | \$ 50.00     | 30    |
| 2                                                       | TO REMOVE AND REFIT REVERSE SENSOR             | 1     | \$ 150.00                | \$ 150.00    | 30    |
| 3                                                       | REMOVE AND REFIX REAR UPHOLSTERY / CARPET      | 1     | \$ 150.00                | \$ 15.00     | ✗ /   |
| 4                                                       | CHECK AND TEST FOR WATER LEAKAGE               | 1     | \$ 150.00                | \$ 150.00    | X     |
| 5                                                       | REMOVE AND RENEW REAR WINDSCREEN GLASS         | 1     | \$ 150.00                | \$ 150.00    | 120 / |
| 6                                                       | REMOVE AND TRANSFER ALL REAR TAILGATE FITTING  | 1     | \$ 200.00                | \$ 200.00    | 50    |
| 7                                                       | REPAIR AND STRAIGHTEN LH REAR CHASSIS FRAME    | 1     | \$ 350.00                | \$ 350.00    | X     |
| 8                                                       | TO RESPRAY UNDERCOATING                        | 1     | \$ 200.00                | \$ 200.00    | X     |
| 9                                                       | APPLY ANTI RUST ON AFFECTED AREAS              | 1     | \$ 200.00                | \$ 200.00    | 30    |
| 10                                                      | SPRAY PAINTING ON AFFECTED AREAS               | 1     | \$ 1,200.00              | \$ 1,200.00  | 1000  |
| 11                                                      | PANEL BEATING ON AFFECTED AREAS                | 1     | \$ 1,800.00              | \$ 1,800.00  | 1200  |
|                                                         |                                                |       |                          | \$ 4,465.00  |       |
| Steve (LKK) MC Phil<br>17/4/20 L/S, 10 days<br>By AC Jy |                                                |       | Parts Replacement Amount | \$ 14,748.10 |       |
|                                                         |                                                |       | Total Amount for Labour  | \$ 4,465.00  |       |
|                                                         |                                                |       | Total Amount             | \$ 19,213.10 |       |