



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

- Third party survey is on a ~~various~~ ~~prepaid~~ ~~base~~
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimation

RJ (Steve)
17/4/20

Date:

15/4/2020

Vehicle:

SJE7312J

Make / Model:

HONDA FIT

Chassis:

GE6-1037804

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR TAILGATE / DD	1	\$ 1,662.70	\$ 1,662.70
2	REAR TAILGATE LOCK / BT	1	\$ 290.10	\$ 290.10
3	REAR TAILGATE LOCK CATCH X NM	1	\$ 48.60	\$ 48.60
4	REAR TAILGATE OUTER GARNISH / DR	1	\$ 325.20	\$ 325.20
5	REAR TAILGATE OUTER HANDLER X NM	1	\$ 139.30	\$ 139.30
6	REAR TAILGATE NUMBER PLATE LAMP X NM	2	\$ 68.40	\$ 136.80
7	REAR TAILGATE OUTER GARNISH LOGO / NC	1	\$ 70.00	\$ 70.00
8	REAR TAILGATE EMBLEM FIT / NC	1	\$ 54.00	\$ 54.00
9	REAR TAILGATE INNER TRIM BOARD / CR4	1	\$ 774.60	\$ 774.60
10	REAR TAILGATE 3RD BRAKE LIGHT X NM	1	\$ 180.60	\$ 180.60
11	REAR TAILGATE LOCK CABLE / TN	1	\$ 89.10	\$ 89.10
12	REAR TAILGATE SHOCK ABSORBER LH X NM	1	\$ 321.50	\$ 321.50
13	REAR TAILGATE SHOCK ABSORBER RH X NM	1	\$ 321.50	\$ 321.50
14	REAR TAILGATE HING LH / BT	1	\$ 92.50	\$ 92.50
15	REAR TAILGATE HING RH X NM	1	\$ 92.50	\$ 92.50
16	REAR TAILGATE RUBBER STOPPER LH X NM	1	\$ 14.20	\$ 14.20
17	REAR TAILGATE RUBBER STOPPER RH X NM	1	\$ 14.20	\$ 14.20
18	REAR TAILGATE WIPER MOTOR X NM	1	\$ 448.70	\$ 448.70
19	REAR TAILGATE WIPER MOTOR ARM X NM	1	\$ 112.30	\$ 112.30
20	REAR TAILGATE WIPER BLADE X NM	1	\$ 36.40	\$ 36.40
21	REAR TAILGATE WIRE HARNESS X NM	1	\$ 445.70	\$ 445.70
22	REAR TAILGATE WINDSCREEN GLASS / DR	1	\$ 1,309.10	\$ 1,309.10
23	REAR TAILGATE WINDSCREEN GLASS MOULDING / NC	1	\$ 135.30	\$ 135.30
24	REAR BOOT WEATHER STRIPE / CR4	1	\$ 203.60	\$ 203.60
25	REAR BUMPER / DD	1	\$ 890.80	\$ 890.80
26	REAR BUMPER SIDE RETAINER LH / DR	1	\$ 80.30	\$ 80.30
27	REAR BUMPER SIDE RETAINER RH / DR	1	\$ 80.30	\$ 80.30
28	REAR END PANEL / DR	1	\$ 796.60	\$ 796.60
29	REAR END PANEL TOP GARNISH / CR4	1	\$ 260.80	\$ 260.80
30	REAR SPARE TYRE COMPARTMENT X NM	1	\$ 1,237.73	\$ 1,237.73
31	REAR SPARE TYRE TOP COVER BOARD / TN	1	\$ 292.30	\$ 292.30
32	REAR SPARE TYER SPONGE / CR4	1	\$ 221.40	\$ 221.40
33	REAR FLOOR PANEL RH X NM	1	\$ 226.70	\$ 226.70
34	REAR FLOOR PANEL LH X NM	1	\$ 226.70	\$ 226.70
35	REAR TAILLAMP LH / DR	1	\$ 516.20	\$ 516.20
36	REAR TAILLAMP LOWER BRACKET LH X NM	1	\$ 65.30	\$ 65.30
37	REAR TAILLAMP INNER PANEL LH / BT	1	\$ 178.30	\$ 178.30
38	REAR TAILLAMP CLIPS LH / NC	2	\$ 6.50	\$ 13.00

796/

232/

X

245/

X

X

X

/

/

341/

X

/

X

X

X

/

X

X

X

X

X

X

X

X

1180/

85/

/

495/

/

/

480/

215/

X

/

/

/

X

X

/

X

/

5.91/

SJE7312J

39	REAR TAILLAMP RH ? / DR	1	\$ 516.20	\$ 516.20	✓
40	REAR TAILLAMP LOWER BRACKET RH ? X NAI	1	\$ 65.30	\$ 65.30	X
41	REAR TAILLAMP INNER PANEL RH X NAI	1	\$ 178.30	\$ 178.30	X
42	REAR TAILLAMP CLIPS RH ? / MC	2	\$ 6.50	\$ 13.00	5.00 /
43	LH REAR FENDER / DD	1	\$ 752.40	\$ 752.40	✓
44	LH REAR FENDER AIR VENT ? X NAI	1	\$ 62.40	\$ 62.40	X
45	LH REAR FENDER INNER COWLING / MC	1	\$ 91.50	\$ 91.50	✓
46	LH REAR FENDER INNER TRIM BOARD BOTTOM ? / CRH	1	\$ 643.80	\$ 643.80	582 ✓
47	LH REAR FENDER INNER TRIM BOARD TOP ? / DR	1	\$ 228.60	\$ 228.60	✓
48	RH REAR FENDER X R	1	\$ 752.40	\$ 752.40	X
49	RH REAR FENDER AIR VENT X NAI	1	\$ 62.40	\$ 62.40	X
50	RH REAR FENDER INNER COWLING X NAI	1	\$ 91.50	\$ 91.50	X
51	RH REAR FENDER INNER TRIM BOARD BOTTOM X NAI	1	\$ 643.80	\$ 643.80	X
52	RH REAR FENDER INNER TRIM BOARD TOP X NAI	1	\$ 228.60	\$ 228.60	X
				\$ 16,735.13	
			Less 20%	\$ 3,347.03	
			Total	\$ 13,388.10	
	S/Nett items:				
1	REAR REVERSE SENSOR / SL	1 SET	\$ 250.00	\$ 250.00	200
2	REAR BUMPER CLIP / MC	1 SET	\$ 80.00	\$ 80.00	30
3	REAR END PANEL GARNISH CLIP / MC	1 SET	\$ 30.00	\$ 30.00	20
4	FLOOR PANEL SEALANT X NAI	1	\$ 50.00	\$ 50.00	X
5	END PANEL SEALANT / MC	1	\$ 50.00	\$ 50.00	30
6	LH REAR FENDER INNER TRIM BOARD CLIPS / MC	1 SET	\$ 80.00	\$ 80.00	20
7	RH REAR FENDER INNER TRIM BOARD CLIPS X NAI	1 SET	\$ 80.00	\$ 80.00	X
8	REAR TAILGATE INNER TRIM BOARD CLIPS / MC	1 SET	\$ 80.00	\$ 80.00	20
9	REAR WINDSCREEN GLASS SEALANT / MC	1	\$ 60.00	\$ 60.00	✓
10	REAR REVERSE CAMERA X NAI	1	\$ 300.00	\$ 300.00	X
11	MISCELLANEOUS X NAI		\$ 300.00	\$ 300.00	X
				\$ 1,360.00	
	Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00	30
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00	30
3	REMOVE AND REFIX REAR UPHOLSTERY / CARPET	1	\$ 150.00	\$ 150.00	15.00 ✓
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00	X
5	REMOVE AND RENEW REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	120 ✓
6	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 200.00	\$ 200.00	50
7	REPAIR AND STRAIGHTEN LH REAR CHASSIS FRAME	1	\$ 350.00	\$ 350.00	X
8	TO RESPRAY UNDERCOATING	1	\$ 200.00	\$ 200.00	X
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	30
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00	1000
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00	1200
				\$ 4,465.00	4,600.00
Steve (LKK) MC Mil 17/4/20 L/S, 10 days My AC Jy			Parts Replacement Amount	\$ 14,748.10	
			Total Amount for Labour	\$ 4,465.00	4,600.00
			Total Amount	\$ 19,213.10	

L/S = \$7,500.00

19,348.10

10 repair days