



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

## Estimation

Date:

16/4/2020

Vehicle:

SLQ2732B

Make / Model:

RENAULT MEGANE

Chassis:

VF1RFB00156852572

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR TAILGATE / (Fibre type) DR (with garnish)			
2	REAR TAILGATE LOCK / BT			
3	REAR TAILGATE LOCK CATCH X			
4	REAR TAILGATE LOWER GARNISH X			
5	REAR TAILGATE INNER TRIM BOARD X			
6	REAR TAILGATE EMBLEM LOGO / MC			
7	REAR TAILGATE EMBLEM MAGANE / MC			
8	REAR TAILGATE EMBLEM GT / MC			
9	REAR TAILGATE EMBLEM ONE / MC			
10	REAR TAILGATE LAMP LH X			
11	REAR BUMPER / DR			
12	REAR BUMPER REINFORCEMENT / DO			
13	REAR BUMPER REINFORCEMENT GARNISH COVER ? (LH) / MIS			
14	REAR BUMPER REINFORCEMENT COVER LH ? X			
15	REAR BUMPER SIDE RETAINER LH / DR			
16	REAR BUMPER SIDE RETAINER RH / DR			
17	REAR BUMPER UNDER COVER ? X			
18	REAR BUMPER TOW COVER / MIS			
19	REAR BUMPER LOWER GARNISH / CUT			
20	REAR BUMPER LOWER GRILLE ? X			
21	REAR BUMPER REFLECTOR LH ? / DR			
22	REAR TAILLAMP LH / DR			
23	REAR TAILLAMP LOWER BRACKET LH ? X			
24	REAR END PANEL ? / DO			
25	REAR END PANEL TOP GARNISH ? X			
26	REAR EXHAUST MUFFLER X			
27	REAR BOOT WEATHER STRIPE / TN			
				\$ -
			Less 10%	\$ -
			Total	\$ -

Rear Bump top bracket / CR4

Rear Bump sponge / DR

## SLQ2732B

S/Nett items:				
1	REAR REVERSE SENSOR / SLA	62	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP / MC	1 SET	\$ 80.00	\$ 80.00
3	REAR END PANEL GARNISH CLIP / MC	1 SET	\$ 30.00	\$ 30.00
4	FLOOR PANEL SEALANT ?	1	\$ 50.00	\$ 50.00
	REAR WINDSCREEN GLASS SEALANT / MC	1	\$ 60.00	\$ 60.00
5	END PANEL SEALANT ?	1	\$ 50.00	\$ 50.00
6	MISCELLANEOUS X	1	\$ 200.00	\$ 200.00
				\$ 720.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 150.00	\$ 150.00
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 120.00	\$ 120.00
5	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	\$ 150.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 120.00	\$ 120.00
8	TO RESPRAY UNDERCOATING	1	\$ 120.00	\$ 120.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 2,490.00
			Parts Replacement Amount	\$ 720.00
			Total Amount for Labour	\$ 2,490.00
			Total Amount	\$ 3,210.00

Steve (LKK) WML M/L  
 20/4/22, 10.00am  
 L/S  
 My AL sy  
 5 dys

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: