

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	front bumper ✓	deformed	\$ 1,020.70	\$ 1,020.70
2	1 pc	front bumper sponge X n n	unconfirmed	\$ 128.70	not affected
3	1 pc	front bumper l/h side retainer X n n	necessary	\$ 85.10	\$ 85.10
4	1 pc	front bumper r/h side retainer X n n	necessary	\$ 85.10	\$ 85.10
5	1 set	front bumper clips ✓	necessary	\$ 35.00	\$ 35.00
6	1 pc	front logo emblem ✓	necessary	\$ 87.10	\$ 87.10
7	1 pc	r/h headlamp X n n	cracked	\$ 2,531.60	\$ 2,531.60
				\$ 3,973.30	\$ 3,844.60
		Less 25%			\$ 961.15
				\$ 3,973.30	\$ 2,883.45
Sub - Total				\$ 3,973.30	\$ 2,883.45

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 3,973.30	\$ 2,883.45
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 800.00	\$ 200 600.00
2		To realign headlamp focus		\$ 35.00	\$ X 20.00
3		To check wiring and rewire		\$ 60.00	\$ X 50.00
4		To putty and spray-paint of affected areas		\$ 600.00	\$ 200 400.00
				\$ 1,495.00	\$ 1,070.00
Sub - Total				\$ 5,468.30	\$ 3,953.45