



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101226

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/03/2021
Reference CC6/CTI20005284/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 9393P
Insured Veh. GBK 1513Z
Claim No. SNM20D201797
Policy No. DMCVSNW00005322000
Accident Date 16/04/2020
Inspection Date 17/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20005284/Aea3q2 Date: 01/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 1513Z	Veh. Inspected	SKZ 9393P	
Policy No.	DMCVSNW00005322000	Coverage (\$)	0.00	
Claim No.	SNM20D201797	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12060DX49324	Colour	BLUE	
Odometer	126763 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/55 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/55 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/55 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/04/2020	Inspection Date	17/04/2020	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 9393P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,563.00	1,563.00
1	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE HOLDER @\$141.50	NOT NECESSARY	283.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	38.00	-
1	REAR BUMPER INNER FRAME	CRACKED	210.00	210.00
1	REAR BUMPER REINFORCEMENT	BENT	697.00	697.00
2	REVERSE SENSOR	DAMAGED (1 PCS ONLY)	530.00	265.00
1	TAILLAMP LH	CRACKED	572.00	572.00
1	BMW LOGO	NOT NECESSARY	68.00	-
1	520I EMBLEM	NOT NECESSARY	61.00	-
	LESS 10% DISCOUNT		-	-335.70
			4,072.00	3,021.30
	<u>LABOUR</u>			
	PANEL BEATING .		500.00	250.00
	SPRAY PAINTING .		500.00	250.00
	WIRING .		50.00	30.00
	TO REMOVE REVERSE SENSOR .		150.00	60.00
	TO PERFORM DIANOGSTIC TEST	NOT NECESSARY	200.00	-
			1,400.00	590.00
	GRAND TOTAL		5,472.00	3,611.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00

Report Ref No. CC6/CTI20005284/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 9393P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 9393P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

