

Estimate Report

04/18/2020

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:	5108783736	Date of Loss:	19/3/2020
Vehicle Reg. No.:	FBL5366A	Driveable?	no
Driver Age:	10/7/1973	Third Party Vehicle No.:	SMA1896R
Any Injuries?	no	Contact No:	90226543
Insured/Claimant:	SHUNMUGAM BALASUBRAMANIAN	Driver:	SHUNMUGAM BALASUBRAMANIAN

Make/Model:	Harley Davidson, STREET GLIDE SPACIAL	Vehicle Reg. Date:	02/04/2020
Vehicle Colour:		Engine Number:	
Chassis No:	5HD1KRCC0HB608357	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	820.00
Paintwork Labour	560.00
Towing	0.00

Gross Total(S\$):	1,380.00
GST 7.00%(S\$):	96.60
Nett Amount(S\$):	1,476.60

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Report

Not added
 3 days.
 H/S
 04/18/2020

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER <i>DD ✓</i>	0.00	0.00	0.00
2	1	FRONT FORK LH <i>su X</i>	0.00	0.00	0.00
3	1	FRONT FORK RH <i>su X</i>	0.00	0.00	0.00
4	1	FUEL TANK <i>DD X</i>	0.00	0.00	0.00
5	1	FUEL TANK EMBLEM RH <i>su ✓</i>	0.00	0.00	0.00
6	1	ENGINE CRASH BAR (1 SET) <i>su X</i>	0.00	0.00	0.00
7	1	STEERING CONE & BEARING <i>su X</i>	0.00	0.00	0.00
8	1	STEERING UNDER BRACKET <i>su X</i>	0.00	0.00	0.00
9	1	FRONT FORK CENTRE STABILIZER LINK ?	0.00	0.00	0.00
Total Parts (\$\$)					0.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
Sub Total (\$\$)					0.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Conduct Wheel Balancing	60.00	0.00	<i>su</i> 60.00 X
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts. <i>fork</i>	40.00	0.00	<i>su</i> 40.00 X
3	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00 <i>100</i>
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	500.00	0.00	500.00 <i>250</i>
Gross Labour Cost (\$\$)					820.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	<i>su</i> 80.00 X
2	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	<i>su</i> 80.00 X
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	0.00	400.00
Gross Labour Cost (\$\$)					560.00

< END OF ESTIMATES >