BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216) Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 18 Apr 2020

ASSESSMENT FOR REPAIR: YAMAHA GDR155A (AEROX) - FBN2818Y

Chassis No.: Engine No.:

Qty	Description	Estimate
1 pc	Front mudguard rear cover	\$75.00 ?
1 pc	Front mudguard	\$95.00 / 54
1 pc	Wheel axle	\$60.00 × 5V L
1 pc	Brake disk	\$185.00 X SV L
1 pc	Right fork assy	\$420.00
1 pc	Left fork assy	\$420.00 ?
1 pc	Steering stem	\$220.00 ?
2 pcs	Steering stem bearings @ \$45.00	\$90.00 ?
1 pc	Centre cover inner	\$120.00 ?
1 pc	Centre cover lower	\$140.00 ?
1 pc	Front cover gold	\$95.00 ?
1 pc	Front cover gold amblem	\$25.00 ? \$140.00 / CCK
1 pc	Left front fairing	\$140.00
1 pc	Left front fairing amblems	\$35.00 /NEC
1 pc	Right front fairing	\$140.00 ?
1 pc	Right front fairing amblems	\$35.00?
1 pc	Headlamp assy	\$280.00 / CRK
1 pc	Headlamp lower cover	\$85.00 ~ CK
1 pc	Left front signal	\$85.00 ?
1 pc	Left mirror assy	\$55.00 / S CL
1 pc	Left lever	\$55.00 / 5 (4)
1 pc	Handle bar	\$140.00?
1 pc	Left foot step	\$140.00
1 pc	Left footstep rubber	\$65.00 /NEC
1 pc	Side stand Marge	\$85.00
1 pc	Mainstand	\$185.00 / SCC
1 pc	Left engine cover	\$295.00 / S CR
	Airbox assy	\$140.00 / 5 CK
1 pc	Centre inner cover body	\$135.00 ?
1 pc	Rear left suspension	\$250.00 XSV (
1 pc	Real left suspension	
		\$4,290.00
		\$429.00
	Less discount 10%	\$3,861.00
	Special nett items	
		\$140.00 / 5CK
1 pc	Box bracket	ф170.00

1)	Towing charges Replace, realign and adjust above	\$100.00 ×
2)	damaged parts, check wiring and lighting system	\$700.00 3 %
3)	To remove, replace and balance front wheel rim	\$120.00 ?
4)	To knock, straighten chassis & body balancing	\$380.00 2 100
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ? \$300.00 200
6)	Spray painting	,

Total Estimate

Note: The above estimate is subjected to the prevailing GST of 7%

NAZ LKK 415/2020 1330

> L/3 3 DMS

CHECK ITEM PHOTOS

For Bike Production Pte Ltd

\$5,781.00