

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autoteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SMS 2094L
Vehicle Model : TOYOTA VOXY HYBRID
Accident Date : 17.04.2020
Original Reg Date : 14.02.2020

Date : 18.04.2020
Chassis : ZWR800410907
TP Ins. **AIG**

ESTIMATE

1	1 pc	Tailgate		2,195.70	bt
2	1 pc	Tailgate Badge		80.70	del
3	1 pc	Tailgate Emblem Hybrid		91.70	del
4	1 pc	Tailgate Outer Garnish Clips		30.00	X
5	2 pcs	Tailgate Stopper	34.10	68.20	X
6	2 pcs	Tailgate Side Stopper (Male)	46.10	92.20	X
7	2 pcs	Tailgate Side Stopper (Female)	48.10	96.20	X
8	1 pc	Tailgate Pocket Handle		59.40	del
9	1 pc	Tailgate Inner Trim		920.70	del
10	1 set	Tailgate Inner Trim Clips		40.00	del 30
11	1 pc	Tailgate Inner Lock * photo		434.50	bt
12	1 pc	Tailgate Lock Catch		68.10	Rp
13	1 pc	Tailgate Weatherstrip		327.50	del
14	2 pcs	Tailgate Hinges	104.10	208.20	Rp
15	2 pcs	Tailgate Absorber	395.10	790.20	Rp
16	2 pcs	Rear Windscreen Moulding	90.00	180.00	del
17	1 pc	Rear Windscreen Inner Seal		50.00	del
18	1 pc	Rear Bumper		1,247.10	del
19	2 pcs	Rear Bumper Side Retainers	59.10	118.20	LH-del, RH-X
20	2 pcs	Rear Bumper Attachment Retainers	61.70	123.40	LH-del, RH-X
21	1 set	Rear Bumper Clips		50.00	30 del
22	2 pcs	Rear Bumper Reflectors	51.70	103.40	X
23	1 pc	End Panel		785.60	bt
24	1 pc	End Panel Top Trim		321.50	del
25	1 set	End Panel Top Trim Clips		30.00	del
26	1 pc	Rear Floor Panel Top Board		691.50	del
27	1 pc	Rear Key Antenna		324.10	del
28	2 pcs	Rear Fender Inner Trims	924.10	1,848.20	LH-del, RH-X
29	2 pcs	Rear Fender Inner Trims Clips	30.00	60.00	del 30

11,436.30

Less 25% 2,859.08

C/F **8,577.23**

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SMS 2094L

B/F

8,577.23

Special Nett

1	1 pc	Rear Windscreen Sealant	60.00
2	1 pc	Rear Number Plate	70.00
3	1 set	Reverse Sensor	250.00
4	1 set	Body Panel Joint Sealant	120.00

rec
45x
200mm
4 Over

Labour Charge

Panel Beating	1,000.00
Spray painting	1,000.00
Check Wiring	50.00
Anti rust	90.00
Remove and install rear windscreen.	140.00
Remove and install tailgate parts.	90.00
Remove and install carpet and seats	120.00
Remove and install reverse sensor	90.00
Remove and install rear camera.	120.00

700
700
30
30
120
60
60
30
30

11,777.23

Less 20% 2,355.45
Lump sum 9,421.78

Tan Jiah 97445744

WP
20/4/2020 330pm

Lump sum

Pay after repair

06 days

Tan Jiah C Khanda w.m.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: