

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35363

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0379/2020/NS
Date : 16-Apr-20

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

294224

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chua Swee Boon (Cai Ruiwen)
Address : Blk 609 Ang Mo Kio Avenue 4
#10-1169
Singapore 560609
Telephone : (HP) +65 94306852
Type of Claim : Own Damage Claim
Policy No. : 1700063199-02
Vehicle No : **SGH 7637 S**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 11/10/2017
Engine No : CVN 041412
Chassis No : WAUZZZF4XHA182059
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Apr-20
Place of Accident : In Front Blk 607 Ang Mo Kio Avenue 4

Premium Automobiles

33 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1184

Telefax

Estimated Labour Charges for Accident Vehicle. SGH 7637 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$ 360.00 ✓	360.00
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00	1000 ✓ 1000.00
3	To respray front bumper, lhs front fender, bonnet and hinges. ✓ ✓ ✓	\$ 3,200.00	1650 ✓ 1650.00
4	To carry out diagnostic check.	S/N \$ 192.00	192.00
TOTAL LABOUR CHARGES		: \$ <u>6,902.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGH 7637 S

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>2hd</i>	\$	2,010.00 ✓	1608.00
2	FRONT BUMPE FIXING PARTS <i>2</i>	\$	269.00 ✗	
3	FRONT BUMPER SECURING STRIP <i>2</i>	\$	67.00 ✗	
4	FRONT BUMPER GRILLE - CENTRE <i>Not m</i>	\$	185.00 ✗	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not m</i>	\$	198.00 ✗	
6	FRONT BUMPER AIR GUIDE - LH <i>Not m</i>	\$	59.00 ✗	
7	RADIATOR GRILLE <i>Crack</i>	\$	1,714.00 ✓	1371.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>2</i>	\$	344.00 ✗	
9	FRONT BUMPER FOAM FILLER PIECE	\$	117.00 ✗	
10	FRONT BUMPER CARRIER	\$	757.00 ✗	
11	FRONT BUMPER COVER	\$	120.00 ✗	
12	FRONT BUMPER GUIDE SECTION - LH <i>Not m</i>	\$	34.00 ✗	
13	CAUTION SIGN STICKER <i>2</i>	NEC \$	13.00 ✓	
14	AIRCON STICKER <i>Not m</i>	NEC \$	7.00 ✗	
15	LOCK CARRIER BRACKET	\$	129.00 ✗	
16	FRONT BUMPER SUPPORT - LH / RH <i>Not m</i>	2 \$	54.00 ✗	
17	HORN - LH HIGH TONE <i>2</i>	\$	38.00 ✗	
18	SPRING SHACKLE - LH <i>Not m</i>	\$	27.00 ✗	
19	FRONT FENDER - LH <i>Repair</i>	\$	722.00 ✗	
20	FRONT FENDER ATTACHMENT PARTS <i>Not m</i>	\$	190.00 ✗	
SUB TOTAL SPARE PARTS		:	\$ 7,054.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGH 7637 S

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	FRONT FENDER CLOSING ELEMENT - LH	\$	47.00	+
22	FRONT FENDER BRACKET - LH	\$	33.00	+
23	DEFORMATION ELEMENT BRACKET - LH	\$	46.00	+
24	FRONT FENDER BRACKET	\$	30.00	+
25	FRONT FENDER BRACE - LH FRONT	\$	112.00	+
26	WHEEL HOUSING LINER - LH	\$	226.00	+
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	86.00	+
28	WHEEL SPOILER	\$	69.00	+
29	WHEEL SPOILER TRIM - LH	\$	33.00	+
30	STONE CHIP GUARD	\$	48.00	✓ 37.92
31	TOP FENDER LEDGE COVER - LH INNER	\$	29.00	+
32	TOP FENDER LEDGE COER - LH OUTER	\$	21.00	+
33	BONNET	\$	2,634.00	✓ 2107.20
34	BONNET ATTACHMENT PARTS	\$	116.00	+
35	BONNET LID HINGE - LH / RH	\$	574.00	+
36	BONNET IMPACT PROTECTION - LH / RH / CENTRE	\$	78.00	+
37	LED HEADLIGHT - LH	\$	7,321.00	+
38	LEFT CYLINDER - LH	\$	198.00	+
39	FRONT NO PLATE	S/N \$	60.00	✓ 60.00
40	SUNDRIES	\$	300.00	? 61.92
TOTAL SPARE PARTS		:	\$ 19,115.00	
TOTAL LABOUR CHARGES		:	\$ 6,902.00	
GRAND TOTAL		:	\$ 26,017.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Adnan (j)
Surveyed Date : 21/04/10
Authorised Date :
Excess Cost :
Liability :
Remarks : All Authorised, 05 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant