

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 20/04/2020

Yvonne

TO:

Auto & General Insurance (Singapore) Pte Limited

190 Clemenceau Avenue

#03-01 Singapore Shopping Centre

Singapore 239924

Our Customer: Clarence Bhagya Raj S/O Terence

Selvarai

Vehicle No: SKW1567Z

Model: Mercedes Benz B200 AT ABS

Manufacture Year: 2013

Date of Accident: 19/04/2020

Total Estimate Repair Days: 2

Attn: Motor Claims Department

Total Pages: 1

Fax: 6725 0853

Re: Repair Estimate For Third Party Claim against SGW2266H

WND2462432J195278

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				/
1	Side mirror mechanism RH Doge	1	\$868.00	\$868.00	
2	Side mirror glass RH Could	1	\$499.00	\$499.00	
3	Side mirror cover bottom RH	1	\$78.00	\$78.00	X
4	Side mirror cover w/signal lamp RH LL	1	\$380.00	\$380.00	7/85.
5	Front door RH	1	repair	repair	X
	Total			\$1,825.00	1532
	Less 10%			\$182.50	120/10
	Sub-Total 1			\$1,642.50	12 70 0
В.	Labour				
1	To check wiring.			\$50.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$200.00	100 23
3	Spray painting all affected parts & areas.			\$400.00	100.
	Total Labour			\$650.00	
	Total Repair Cost			\$2,292.50	

Yours faithfully,

Aun Teng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

f Premium Carz Services Pte Ltd Pte Ltd Signature:

Date:

Surveyor's Details Adrian Name 96893735 Contact 21/04/20 Survey Date Authorize / Not Authorize Recommender Before Paint Yes / No

