

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.Khan@premiumauto.com.sg claims@premiumauto.com.sg

WIP : 35134

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0363/2020/NS
Date : 6-Apr-20

Jasper

Vehicle NOT IN workshop. Please arrange for survey

Total : 1647.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Devdatt Vijay Nerurkar
Address : 68 Bayshore Road
#25-04
Singapore 469986
Telephone : HP +65 93849586
Type of Claim : Third Party Claims
Policy No. : 1900105789
Vehicle No : **SML 8929 B**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Jun-19
Engine No : CHZ C29866
Chassis No : WAUZZZ8VXKA074327
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-20
Place of Accident : Amber Road And Mountbatten Road Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 8929 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	500
3	To respray rear bumper.	\$ 900.00	500 550.
4	To reapply paint coating. (By owner)	S/N IBC	↑ 25.
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 8929 B

		Damage Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
1	REAR BUMPER <i>Regis</i>	\$ 1,851.00	X
2	REAR BUMPER STICKY PAD	4 \$ 22.00	X
3	REAR BUMPER FIXING PARTS	\$ 182.00	✓
4	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 30.00	X
5	REAR BUMPER LOCKING MECHANISM	2 \$ 55.00	X
6	REAR BUMPER SPOILER	\$ 223.00	X
7	REAR LIGHT REFLECTOR - LH / RH	2 \$ 78.00	X
8	REAR BUMPER SIDE REINFORCEMENT BEAM	\$ 538.00	X
9	REAR BUMPER BRACKET - LH	\$ 26.00	✓
10	REAR BUMPER BRACKET - RH	\$ 27.00	✓
11	REAR PARKING AID SENSOR - INNER / OUTER	2 TBC	X
12	REAR PARKING AID SEAL RING	4 \$ 14.00	✓
13	SUNDRIES <i>pl per</i>	\$ 200.00	X
TOTAL SPARE PARTS CHARGES		: \$ 3,246.00	
TOTAL LABOUR CHARGES		: \$ 2,422.00	
GRAND TOTAL		: \$ 5,668.00	

All charges are not inclusive of GST.
Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Name

: Adam Lij

Surveyed Date

: 20/04/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 03 Days

HS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant