



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1174P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	PANEL ASSY-QUARTER OUTER		1,768.30	-
	LESS 20% DISCOUNT		-353.66	-
			1,414.64	-
1	<u>NETT ITEMS</u>	NECESSARY		
	FUEL TANK LID (PETROL ONL (N)		15.00	15.00
	LESS 10% DISCOUNT		-1.50	-1.50
			13.50	13.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PANEL ASSY-QUARTER OUTER.		960.00	320.00
	SPRAYPAINT CHARGE.		300.00	200.00
			1,260.00	520.00
GRAND TOTAL			2,688.14	533.50
RECOMMENDED COST OF REPAIRS (CONFIRMED)				533.50

Report Ref No. NS/INC20005304/Fyf3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.