

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 #01-28/55 (417883)

VEHICLE No: SGS 515Z

1PC REAR BUMPER
1PC REAR BUMPER SIDE RETAINER N/S
1SET REAR BUMPER CLIPS
1PC REAR FENDER N/S
1PC REAR SPORT RIM N/S

20/10/11 \$1,266.60
11 \$35.00 X
11 \$50.00 X
11 \$1,196.20 X
11 \$850.00 X
\$3,397.80

20%

TO CHECK WIRING
TO DISMANTLE & REFIX REVERSE SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 50
\$120.00 60
11 \$80.00 X
11 \$120.00 X
\$680.00 300
\$800.00 400
TOTAL \$5,327.80

not Authorised
LKK
27/4/20
2/5 @ 1500
3 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1316-60
20%
P-1053-28
L-830.00
1883.28
202
1506.