



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2004537  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE INV Date 24/06/2020  
SINGAPORE 189556 Reference CS/INC20005306/Usf3n2  
ATTN: JULIANA Code INC



### PROFESSIONAL SERVICE FEE

Vehicle No. SGS 515Z  
Insured Veh. SJL 4749R  
Claim No. MT/1083521-002  
Policy No.  
Accident Date 02/02/2020  
Inspection Date 27/04/2020

Description	Total
Damage Assessment	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20005306/Usf3n2

73 BRAS BASAH ROAD

Date: 24-06-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: JULIANA

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 4749R	Veh. Inspected	SGS 515Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1083521-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	21/04/2020

#### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6GL1071H0108793	Colour	BLACK
Odometer	62540 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	02/02/2020	Inspect Date / Time	27/04/2020 ( 11:17 AM )
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 515Z**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED / TORN	1,266.60	1,266.60
1	REAR BUMPER SIDE RETAINER N/S	NOT NECESSARY	35.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,196.20	-
1	REAR SPORT RIM N/S	NOT NECESSARY	850.00	-
	LESS 20% DISCOUNT		-	-263.32
			3,397.80	1,053.28
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	60.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		680.00	300.00
	TO PUTTY & SPRAY PAINTING.		800.00	400.00
			1,930.00	830.00
	<b>GRAND TOTAL</b>		<b>5,327.80</b>	<b>1,883.28</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,500.00</b>

Report Ref No. CS/INC20005306/Usf3n2

**CHUA KANG SENG**

Licensed Appraiser

**K.K.LAU CPT(RET)****BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SGS 515Z

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 515Z

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SGS 515Z**

**RE-INSPECTION**

