



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100953

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/02/2021
Reference CC4/FCI20005307/Dpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. JQY 3455
Insured Veh. SHD 3568T
Claim No. D20001799MFSH
Policy No. D-20094922MFSH
Accident Date 02/04/2020
Inspection Date 21/04/2020

Description	Total
Survey Inspection	377.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	377.00
GST (7%)	26.39
Grand Total	403.39

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20005307/Dpa3q2	
			Date: 10/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3568T	Veh. Inspected	JQY 3455	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001799MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	21/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	PMYUG0310F0234326	Colour	BLUE	
Odometer	66759 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	DUNLOP	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80 R17	DUNLOP	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/04/2020	Inspection Date	21/04/2020	
Survey held at	S9 MOTOR TRADING PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQY 3455

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT / DISTORTED	135.00	135.00
1	HANDLE BAR BRACKET	NOT NECESSARY	95.00	-
1	SET MIRROR N/S	CUT	150.00	75.00
1	FRONT MUDGUARD	BROKEN	215.00	215.00
1	SET FORK TUBE	BENT	480.00	480.00
1	FORK UNDERBRACKET	DAMAGED	168.00	168.00
1	FRONT DISC	NOT NECESSARY	260.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	320.00	-
1	BRAKE LEVER	NOT NECESSARY	70.00	-
1	CLUTCH LEVER	CUT	75.00	75.00
1	HEADLAMP ASSEMBLY	CUT / SCRATCHED	325.00	325.00
1	HEAD LAMP TOP COVER	CUT	255.00	255.00
1	FRONT PANEL	CUT	160.00	160.00
1	INNER PANEL	NOT NECESSARY	190.00	-
1	SET BALANCER N/S	CUT	150.00	75.00
1	FRONT LH SIDE PANEL	CUT	125.00	125.00
1	REAR LH TAIL PANEL	BROKEN	150.00	150.00
1	PILLION GRIP	CUT	85.00	85.00
1	FRONT FOOT REST LH	BROKEN	70.00	70.00
1	FRONT FOOT REST BRACKET	NOT NECESSARY	90.00	-
1	FRONT LEG SHIELD	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-365.80	-239.30
			3,292.20	2,153.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	15.00	15.00
1	FRONT NUMBER PLATE (SN)	NECESSARY	20.00	12.00
			35.00	27.00
	<u>LABOUR</u>			
	TOWING FEES.	NOT NECESSARY	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE NECESSARY PARTS,REALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT RIM.		250.00	150.00
	REMOVE & REPLACE FORK TUBE,OIL SEAL & TOP UP FORK OIL,FRONT RIM/DISC.		200.00	80.00
	SUPPLY BODY STICKER/PAINTING.		120.00	100.00
	BODY ALIGNMENT.		220.00	80.00
			840.00	410.00
GRAND TOTAL			4,167.20	2,590.70
RECOMMENDED COST OF REPAIR SUM				1,500.00

Report Ref No. CC4/FCI20005307/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JQY 3455

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JQY 3455

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JQY 3455

RE-INSPECTION

