

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 20 April 2020

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : JQY 3455

Yamaha 135LC

ACCIDENT DATE: 2nd April 2020

Description	Qty	Quotation \$
1 Handle Bar <i>distorted</i>	1	135.00 ✓
2 Handle Bar Bracket <i>NH</i>	1	95.00 ✗
3 Mirror <i>1/3 cut</i>	1 set	150.00 ✓ 76.00
Front Mudguard <i>broken</i>	1	215.00 ✓
4 Fork Tube <i>1st</i>	1 set	480.00 ✓
5 Fork Underbracket <i>2 Dam</i>	1	168.00 ✓
6 Front Disc <i>NH</i>	1	260.00 ✗
7 Front Rim <i>ray</i>	1	320.00 ✗
8 Braker Lever <i>NH</i>	1	70.00 ✗
9 Clutch Lever <i>cut</i>	1	75.00 ✓
10 Headlamp Assembly <i>cut / scratched</i>	1	325.00 ✓
11 Head Lamp Top Cover <i>cut</i>	1	255.00 ✓
12 Front Panel <i>cut</i>	1	160.00 ✓
Inner Panel <i>NH</i>	1	190.00 ✗
13 Balancer <i>1/2 cut</i>	1 set	150.00 ✓ 75.00
14 Front LH Side Panel <i>cut</i>	1	125.00 ✓
15 Rear LH Tail Panel <i>broken</i>	1	150.00 ✓
16 Pillion Grip <i>cut</i>	1	85.00 ✓
17 Front Foot Rest LH <i>broken</i>	1	70.00 ✓
18 Front Foot Rest Bracket <i>NH</i>	1	90.00 ✗
19 Front Leg Shield <i>NH</i>	1	90.00 ✗

Sub-Total 3,658.00

Less 10% 365.80

Sub-Total 3,292.20

LKK Auto Consultancy hence notify
 the Repairer of the following:
 • To resurvey before spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

VEHICLE NO : JQY 3455

Yamaha 135LC

Nett items

1	Towing fees	NH	50.00	X
2	Remove & replace necessary parts, realign & etc		250.00	150/-
3	Supply body sticker	Painting	120.00	100/-
4	Remove & replace fork tube, oil seal & top up fork oil, Front Rim /Disc		200.00	80/-
5	Rear Number Plate	1st	15.00	L
6	Front Number Plate	NH	20.00	12/-
			437.00	

7. Body alignment ~~\$220.00~~

Sub-Total

655.00

80/-

Nett Total

3,947.20

NB: This estimate was made from a visual inspection only, any other damage, parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



S9 TRADING PTE LTD

21/04/2020 c 1700hr

Not Andre

2/5mm 4 days

you

2 KK Andre

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: