

ASS. REC. BY:

REF:

C72/20005308/KF

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLZ 1077T

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

135195

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7

1208208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

10/4/20

D.O.I.

13/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

\$ - RS. SI

: Fuel

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Chuan  
Tarping  
LKK 5/5/20 (Jmes).



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLZ 1077 T

Parts	(a) Cost / List Price Items	\$	1,836.40
	Plus/Less 25%	\$	459.10
	Total of Cost / List	\$	1,377.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
	Total Parts Cost		
Labour		\$	1,300.00
Total		\$	2,677.30

The above total will be subjected to 7% G.S.T.

NOT Authorized  
Repair By paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 13/5/20 at 11am

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : De Date: 13/5/20





**ESTEEM  
PERFORMANCE**

## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts


Vehicle No. : SLZ 1077 T  
Make & Model : HONDA SHUTTLE  
Chassis No : GP71208208

Submit By : Carmen Lim  
Year Manufacture : 2018 Apr  
Engine No. :   
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Deep Cr</i>	1	\$1,150.60		✓
2	Front bumper clip <i>na</i>	10	\$35.00		✓
3	Front bumper side retainer RH <i>sn</i>	1	\$25.40		X
4	RH front fender <i>Bz</i>	1	\$411.90		✓
5	RH front fender undershield <i>sn</i>	1	\$110.50		X
6	RH front fender undershield clip <i>na</i>	10	\$35.00		X
7	RHF fender wording "hybrid" <i>na</i>	1	\$68.00		✓
8					
9	<i>Supplementary :-</i>				
10					
11	<i>Headlamp RH. Cr</i>	1			✓
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N



Submit By : Carmen Lim  
Year of Manufacture : 2018 Apr

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/04/2020 09:26
Date Of Accident	10/04/2020 21:35
Exact Location Of Accident	BLK 7089 HOUGANG AVENUE 2 OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1077T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	2XXXXX651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68386300

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	20-ML000243-R00
Cover Note Number	

### Driver

Name of Driver	HO WHA YONG
NRIC No	SXXXX756J
Date Of Birth	19/03/1953
Occupation	OUTDOOR
Date Of Driving Pass	28/03/1977
Driving Experience	43 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98364389
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 708 HOUGANG AVENUE 2 #07-77
Postcode	530708
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to Police Report: T/20200411/2010.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD7222K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



SKETCH PLAN

A=GLZ-1077T

B=GBD 7222K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer as attached police report .

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11-04-2020 @ 11:50

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GAMUTS-2019-01-01, V.1



Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

1 of 3

Report No. T/20200411/2010

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/04/2020 11:19	Vide Report No.:	Station Diary No.: 32
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: HO WHA YONG			Address: APT BLK 708 HOUGANG AVENUE 2 #07-77 SINGAPORE 530708		
ID Type / ID No.: NRIC NO / S0191756J			Contact No.: Home/Office: Mobile: 98364389		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 67	Date of Birth: 19/03/1953	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Grab driver			Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/04/2020 21:35	Type of Location: Car Park
Location: Along Road 1 HOUGANG AVENUE 2 at B/708 Hougang Ave 2 open carpark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD7222K	Van					0
SLZ1077T	Car					0