

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35080

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0361/2020/NS
Date : 6-Apr-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 14 Jun 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Dr Julian Lee Cheow Yew
Address : 3 Jalan Hajjah
#03-05
Singapore 468698
Telephone : +(65) 97209820
Type of Claim : Own Damage Claims
Policy No. : 1800156747
Vehicle No : **SFE 26 D**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : Dec-18
Engine No : CVK 072389
Chassis No : WAUZZZF50KA006377
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-20
Place of Accident : Car Park BDB 87 Bedok South

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 26 D

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 1,600.00	\$ 500.00
3	To respray front bumper.		\$ 1,200.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
5	To reapply front bumper protection film	S/N	TBC	
TOTAL LABOUR CHARGES		:	\$ 3,472.00	\$ 1,722.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26 D

S/N	Parts Description		<u>Damage Parts & Prices</u>	
			S/Nett	Remarks
1	FRONT BUMPER		\$ 2,142.00	\$ 1,713.60
2	FRONT BUMPER FIXING PARTS		\$ 383.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 67.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 215.00	
6	FRONT BUMPER SPOILER		\$ 504.00	
7	FRONT BUMPER AIR GUIDE - RH		\$ 59.00	
8	RADIATOR GRILLE		\$ 2,190.00	\$ 1,752.00
9	SULTRASOUND SENSOR SUPPORT - LH / RH	2	\$ 98.00	
10	RADIATOR GRILLE COVER - UPPER		\$ 178.00	
11	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 446.00	
12	FRONT BUMPER CARRIER		\$ 757.00	
13	FRONT BUMPER FOAM FILLER PIECE		\$ 117.00	
14	FRONT BUMPER COVER		\$ 120.00	
15	CAUTION SIGN STICKER	NEC	\$ 13.00	
16	AIRCON STICKER	NEC	\$ 7.00	
17	LOCK CARRIER BRACKET		\$ 129.00	
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 54.00	
19	FRONT PARKING AID SENSOR - INNER		TBC	
20	FRONT PARKING AID SEAL RING	4	\$ 14.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 7,678.00	\$ 3,465.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26 D

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
			\$ 3,465.60
21	HORN - RH LOW TONE	\$ 270.00	
22	SPRING SHACKLE - RH	\$ 27.00	
23	WHEEL SPOILER	\$ 69.00	
24	WHEEL SPOILER TRIM - RH	\$ 34.00	
25	LED HEADLIGHT - RH	\$ 7,438.00	
26	LIFT CYLINDER - RH	\$ 187.00	
27	RADIATOR AIR GUIDE - RH	\$ 29.00	
28	RADIATOR AIR GUIDE - RH	\$ 15.00	
29	RADIATOR AIR GUIDE - UPPER	\$ 15.00	
30	RADIATOR AIR GUIDE - LOWER	\$ 21.00	
31	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
32	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 16,143.00	\$ 3,525.60
TOTAL LABOUR CHARGES		\$ 3,472.00	\$ 1,722.00
GRAND TOTAL		\$ 19,615.00	\$ 5,247.60

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant