



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/AXA12019584/Kea3s2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-04-2020



ATTN: STACEY NG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFN 4676D	Veh. Inspected	SHC 5309S
Policy No.	P0565078	Coverage (\$)	0.00
Claim No.	C0236179	Excess (\$)	0.00
Assign From		Assign Date	08/10/2012

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CROWN	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	LXS120020733	Colour	WHITE / RED
Odometer	158843	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/80R14	WEST LAKE	8 mm
L/H Front Tyre	175/80R14	WEST LAKE	8 mm
R/H Rear Tyre	175/80R14	WEST LAKE	7 mm
L/H Rear Tyre	175/80R14	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/10/2012	Inspection Date	08/10/2012
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**