

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5470C****AAD2004-067***Not Authorised  
Resony B4 paint*

Vehicle No.:

Chassis No.:

21 APR 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 5470C**

JTDKB3FU603079168

TOYOTA

PRIUS

18.4.2020

Alh

25/01/2019

**PART**

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO 1
- 1 COVER, FLOOR UNDER, NO 2
- 1 COVER, REAR FLOOR
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 REAR FENDER LINER
- 1 DUCT ASSY, QUARTER VENT, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 PAN, REAR FLOOR
- 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH

**LIST**

\$	Bu	442.60	✓
\$		332.70	?
\$	mtv	15.40	✓
\$	Bu	576.30	✓
\$	Sn	116.50	X
\$	Sn	117.70	X
\$	Bu	1,147.80	✓
\$	CM	925.60	✓
\$	Sn	372.30	X
\$	Sn	650.30	X
\$	CM	502.00	✓
\$	Sn	451.80	X
\$	mtj CM	123.70	✓
\$	Sn	123.70	} X
\$	Sn	502.00	
\$	Sn	443.30	
\$	Sn	126.70	
\$	Sn	175.10	
\$	Sn	241.90	
\$	Sn	229.90	
\$	R	871.50	
\$	Sn	139.80	}
\$	Sn	67.00	
\$	Sn	88.50	
\$	R	583.40	}
\$	Sn	56.50	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5470C

AAD2004-067

<b>TOTAL</b>	<b>\$</b>	<b>9,424.00</b>
<b>25%</b>	<b>\$</b>	<b>2,356.00</b>
	<b>\$</b>	<b>7,068.00</b>

**Special Nett**

1SET	PARKING AID	\$	700.00	X
1SET	REAR BUMPER CLIP	\$	68.00	✓
1	REAR TAILGATE TOYOTA LOGO	\$	47.00	✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	52.90	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	53.50	✓
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	30sm
1	REAR TAILGATE STICKER '6555-3333'	\$	80.00	30sm
1	REAR BUMPER PROTECTOR	\$	120.00	} X
1	WHEEL, RIM	\$	1,879.40	
1	TYRE 195/65/15	\$	350.00	
1	WHEEL RIM COVER	\$	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	35.00	
1	REAR LH BUMPER RETAINER CLIP	\$	35.00	
1SET	TAILLAMP LOWER CLIP	\$	35.00	} X
1SET	TAILLAMP UPPER CLIP	\$	35.00	
2	REAR WINDSCREEN SEALANT	\$	130.00	40sm
1	WINDSCREEN MOULDING	\$	180.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00	30sm
1SET	REAR FENDER LINER CLIP	\$	35.00	X
2	END PANEL SEAM SEALANT	\$	160.00	X
<b>TOTAL</b>		<b>\$</b>	<b>4,407.30</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>11,475.30</b>
--------------------	-----------	------------------

**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	170.00	60l
----	--------	-----

To Rust-Proofing Of The Affected Areas.

\$	170.00	X
----	--------	---

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5470C****AAD2004-067**

To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	6601
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$		170.00	1201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00	4001
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To transfer of Rear Luggage Floor Panel fittings, attachments and perform water seepage test.	\$	nn	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	nn	170.00	X



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5470C

AAD2004-067

TOTAL	\$	17,890.00
-------	----	-----------

Over All Total	\$	29,365.30
----------------	----	-----------

(PART-BY-PART) Repair Days ~~25~~ Days

3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: