

1 Kaki Bukit Ave 2
 #01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
 Singapore 417921 Tel No (65 6842 0081) Fax No (65 6741 0510)
 E-Mail sales@n51.com.sg
 Company Reg No 200616038C
 GST Registration No 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550055 90704034

*(P) 1st copy
 Jacques*

ESTIMATE

Repair Code : CLM16211
 Date in : 21/04/2020
 Vehicle Num : SMA5871K
 Model : TOYOTA SIENTA HYBRID 1.5X CVT
 Chassis/Eng# : NHP1707126823/1NZ8548883

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deboard</i>	1	950.00	<i>750</i> ✓ 950.00
REAR BUMPER CENTER PROTECTOR GARNISH <i>cut</i>	1	209.00	✓ 209.00
REAR BUMPER REFLECTOR L/R <i>Not ne</i>	2	85.00	+ 170.00
REAR BUMPER SIDE PROTECTOR GARNISH L/R <i>Neu</i>	2	155.00	+ 310.00
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	90.00	✓ 180.00
REAR END PANEL 'INNER' <i>Regr</i>	1	607.00	+ 607.00
REAR END PANEL 'OUTER' <i>Dented</i>	1	599.00	✓ 599.00
REAR END PANEL INNER TOP GARNISH <i>Deboard</i>	1	207.00	✓ 207.00
REAR FLOOR COMPARTMENT TRAY <i>Deboard</i>	1	519.00	✓ 519.00
REAR FLOOR COMPARTMENT TRAY TOP BOARD COVER L/R <i>Neu</i>	2	378.00	+ 756.00
REAR TAIL GATE <i>Dented</i>	1	1088.00	✓ 1,088.00
REAR TAILGATE 'HYBRID' EMBLEM <i>Neu</i>	1	78.00	✓ 78.00
REAR TAILGATE 'LOGO' EMBLEM <i>Neu</i>	1	110.00	✓ 110.00
REAR TAILGATE HINGE L/R <i>Neu</i>	2	78.00	X 156.00
REAR TAILGATE INNER PULL GARNISH <i>Neu</i>	1	48.00	+ 48.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>Neu</i>	2	19.00	+ 38.00
REAR TAILGATE INNER TRIM BOARD <i>Neu</i>	1	455.00	X 455.00
REAR TAILGATE LOCK STRIKER <i>Neu</i>	1	40.00	+ 40.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 12 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550055 90704034

ESTIMATE

Repair Code : CLM16211
 Date in : 21/04/2020
 Vehicle Num. : SMA5871K
 Model : TOYOTA SIENNA HYBRID 1.5X CVT
 Chassis/Eng# : NHP1707126823/1NZ8548883

REAR TAILGATE MECHANISM LOCK <i>Dangd</i>	1	265.00	✓	265.00
REAR TAILGATE WEATHER STRIP <i>new cut</i>	1	385.00	✓	385.00
REAR TAILGATE WINDSCREEN MOULDING L/R <i>new</i>	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) <i>new</i>	2	50.00	✓	100.00
Subtotal before discount				7,370.00
Percentage discount 25%				1,842.50
Sub-total 1				5,527.50
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR - SET <i>Dangd</i>	1	300.00	20	300.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	10	40.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	+	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	60	80.00
Subtotal before discount				625.00
Percentage discount 0%				0.00
Sub-total 2				625.00
Parts-total				6,152.50

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LK Auto CONSULTANTS PTE LTD
 #01-08, RAFFLES PLAZA #01-08 MIDVIEW CITY
 SINGAPORE 573060

Contact: 66550055 90704034

ESTIMATE

Repair Code : CLM16211
 Date in : 21/04/2020
 Vehicle Num. : SMA5871K
 Model : TOYOTA SIENTA HYBRID 1.5X CVT
 Chassis/Eng# : NHP1707126823/1NZ8548883

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. 30 ~~100.00~~
- To remove, reinstall tailgate windscreen 120 ~~150.00~~
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) 60 ~~40.00~~
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. 700 ~~1,000.00~~
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 1850 ~~1,000.00~~
- To apply anti-rust chemical on repaired and replaced panel. 60 ~~120.00~~
- To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle. ✓ 80.00

Labour Total 2,590.00
Parts & Labour Total 8,742.50

8,662.50#

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin Lj
 H/S 04/05/20
 06 Days
 Total: 5592.50
 H/S: H4K.