

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000310**

TO : AXA INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 21-APR-2020
 MAKE : MERCEDES BENZ
 MODEL : E 200CGI
 CHASSIS NO : WDD2120482A415106
 ENGINE NO : 27186030215456
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 1

SLX2799Y
LEE CHE HWAY ENOCH
 BLK 102A PUNGGOL FIELD
 #13-436
 SINGAPORE 821102
 CONTACT NO : 96717369

*not added
 22/4/20
 2 shp.
 2 shp. 1 shp.
 22/4/20*

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT GRILLE W/EMBLEM	1247.15	0.00
1	FRONT GRILLE CENTRE BRACKET	100	0.00
1	FRONT BUMPER	1,275.00	0.00
Sub Total		2,880.00	0.00

SPECIAL NETT

4	FRONT SENSOR	1,200.00	0.00
1	NUMBER PLATE W/CASING	60.00	0.00
10	FRONT BUMPER CLIPS	50.00	0.00
Sub Total		1,310.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	600.00	0.00
1	TO SPRAY PAINT ON AFFECTED AREAS	600.00	0.00
1	TO CHECK WIRING	120.00	0.00
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	0.00
1	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT SENSOR & TESTING	150.00	0.00
Sub Total		1,620.00	0.00

SUB-TOTAL

5,810.00 0.00

LKK Auto Consultants hence notify the Repairer of the following:

GST - 7%

406.70 0.00

TOTAL

6,216.70 0.00

ABWIN SERVICE PTE LTD

Acknowledged by Repairer

Signature:

Date:

Prepared By