

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5218R - AXA

RIZA

Not Authorized
21 Sep 81250p

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 5218R - RIZA
 JTDGJ20W305001853
 TOYOTA
 WISH 2.0 BI-FUEL
 21.12.15
AXA

		PART		LIST
1	1	Front Bumper	\$	<i>Bu</i> 585.36 ✓
2	1	Front Bumper Lower Absorber	\$	<i>su</i> 130.00 X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 318.11 X
4	1	Front Bumper Retainer LH	\$	<i>su</i> 74.50 X
5	1	Front Bumper Retainer RH	\$	<i>su</i> 74.50 X
6	1	Front Bumper Fog Lamp RH	\$	<i>Bu</i> 208.00 ✓
7	1	Front Fog Lamp Outer Chrome RH	\$	<i>su</i> 190.00 X
8	1	Front Bumper Fog Lamp Grille RH	\$	<i>su</i> 150.00 X
9	1	Front Headlamp RH	\$	<i>W</i> 672.00 ✓
10	1	Front Headlamp LH	\$	<i>su</i> 672.00 X
11	1	Front Fender RH	\$	<i>R</i> 837.60 X
12	1	Front Fender Liner RH	\$	<i>su</i> 369.14 X
13	1	Windscreen washer tank	\$	<i>su</i> 166.00 X
14	1	Front Support Panel Assy	\$	<i>R</i> 1,222.32 X
15	1	Radiator Grille	\$	<i>su</i> 462.48 X
16	1	Bonnet	\$	<i>R</i> 1,019.16 X
17	1	Bonnet Centre 'TOYOTA' Logo Badge	\$	<i>su</i> 115.44 X

TOTAL	\$	7,266.61
25%	\$	1,816.65
	\$	5,449.96

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>su</i> 50.00 ✓
2	1 Set	Front fender Liner clip RH	\$	<i>su</i> 30.00 X
3	1	Number plate	\$	<i>su</i> 80.00 X
4	1	CNG Sticker	\$	<i>su</i> 30.00 155m
5	1	Tyre FRT RH	\$	<i>su</i> 180.00 X
6	1	Tyre Rim FRT RH	\$	<i>su</i> 120.00 X
7	1	Front fender advertisement sticker RH	\$	<i>su</i> 250.00 X

TOTAL	\$	740.00
TOTAL PARTS	\$	6,189.96

RIZA

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHD 5218R - AXA

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00 <i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	120.00 <i>2001</i>
Putty And Spray Painting Of The Affected	\$	1,350.00 <i>2001</i>
To remove and replace corporate sticker	\$	<i>nn</i> 330.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
	\$	<u>3,760.00</u>
TOTAL	\$	<u>9,949.96</u>

REPAIR DAYS

5 DAYS

1 1/2 days