



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016149/Gvf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 29-04-2020



ATTN : NORSIAH MD NOOR

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 7332C	Veh. Inspected	SLL 9689Z
Policy No.	2100477495	Coverage (\$)	0.00
Claim No.	4824024930SG	Excess (\$)	0.00
Assign From	NORSIAH MD NOOR	Assign Date	22/04/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU XV 1.6	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1GP3KC5HG201079	Colour	WHITE
Odometer	48350	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/05/2018	Inspection Date	04/09/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**