



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 9288D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	596.50	596.50
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	392.60	-
2	REAR BUMPER RETAINER	SERVICEABLE	208.80	-
2	REAR BUMPER RETAINER CENTRE	SERVICEABLE	131.60	-
2	REAR BUMPER REFLECTOR	O/S CRACKED	90.00	45.00
2	REAR BUMPER SENSOR	SERVICEABLE	550.00	-
1	REAR PANEL	TO REPAIR SEE LABOUR	659.60	-
1	REAR PANEL GARISH	SERVICEABLE	195.60	-
1	TAIL BOOT COVER	TO REPAIR SEE LABOUR	819.60	-
1	TAIL BOOT LOGO	NECESSARY	55.80	55.80
1	TAIL BOOT BADGE TOYOTA ALTIS	NECESSARY	78.80	78.80
1	TAIL BOOT BADGE COROLLA	NECESSARY	56.00	56.00
1	TAIL BOOT REFLECTOR RIGHT	CUT	369.60	369.60
1	TAIL BOOT RUBBER	SERVICEABLE	189.00	-
1	TAIL BOOT LOCK	TO REPAIR SEE LABOUR	355.90	-
1	TAIL LAMP RIGHT	CUT	488.90	488.90
	LESS 25% DISCOUNT		-	-422.65
			5,238.30	1,267.95
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER SPOILER (SN)	DENTED / DISTORTED	800.00	600.00
2	REAR BUMPER SPOILER SIDE (SN)	O/S CRACKED	600.00	200.00
			1,400.00	800.00
<b><u>LABOUR</u></b>				
	RUST PROOFING.	NOT NECESSARY	100.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, REAR PANEL, TAIL BOOT COVER AND TAIL BOOT LOCK.		1,200.00	500.00

Report Ref No. CS/TP20005337/Kvf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,000.00	600.00
			2,300.00	1,100.00
<b>GRAND TOTAL</b>			<b>8,938.30</b>	<b>3,167.95</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,550.00</b>

Report Ref No. CS/TP20005337/Kvf3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.