

CK VEHICLE RENTAL PTE LTD

BLK 1003 EUNOS AVE 8 #01-57 (OFF EUNOS ROAD 2)

SINGAPORE 409498

TEL: 67478900

TO	: NTUC INCOME	DATE	: 16/4/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLP9483D	TP INC Independent	
VEHICLE MODEL	: TOYOTA ALLION	Shirley	
CHASSIS NO	:		
ACCIDENT DETAILS	DATE	: 2/4/2020	
	TIME	: 1340 HRS	
THIRD PARTY REQUESTOR / CONTACT	:	XAIVER	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT BUMPER <i>Replaced</i>	1	\$ 791.10	\$ 791.10	<i>7110 ✓</i>
2	FRONT BUMPER CLIPS <i>per</i>	1 SET	\$ 50.00	\$ 50.00	✓
3	FRONT BUMPER SIDE HOLDER LH <i>per</i>	1	\$ 49.00	\$ 49.00	✓
4	HEADLAMP LH <i>lit</i>	1	\$ 809.10	\$ 809.10	✓
5	FRONT LH FENDER <i>Dented</i>	1	\$ 645.20	\$ 645.20	✓
6	FRONT LH FENDER INNER SHIELD <i>Deformed</i>	1	\$ 153.60	\$ 153.60	✓
7	FRONT LH FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
8	FRONT LH DOOR <i>Dented</i>	1	\$ 1,154.60	\$ 1,154.60	✓
9	FRONT LH DOOR LOCK <i>Dented</i>	1	\$ 485.10	\$ 485.10	✓
10	FRONT LH DOOR OUTER HANDLE <i>new</i>	1	\$ 212.60	\$ 212.60	X
11	FRONT LH DOOR BLACK TAPE <i>new</i>	1	\$ 85.00	\$ 85.00	✓
12	REAR LH DOOR <i>Dented</i>	1	\$ 1,245.20	\$ 1,245.20	✓
13	REAR LH DOOR LOCK <i>Dented</i>	1	\$ 450.40	\$ 450.10	✓
14	REAR LH DOOR BLACK TAPE <i>new</i>	1	\$ 85.00	\$ 85.00	✓
15	FRONT LH LOWER ARM <i>2</i>	1	\$ 387.90	\$ 387.90	X
16	FRONT LH KNUCKLE ARM <i>per</i>	1	\$ 399.50	\$ 399.50	+
17	FRONT LH WHEEL HUB C/W BEARING <i>per</i>	1	\$ 210.10	\$ 210.10	+
18	FRONT LH SHOCK ABSORBER <i>per</i>	1	\$ 381.80	\$ 381.80	+

19 Sill Panel RH.

Repaired

6033

452475

TOTAL PRICE:

\$ 6,904.90

LESS 25%

\$ 1,726.23

SUB TOTAL PRICE:

\$ 5,178.68

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT LH WHEEL RIM <i>ut</i>	1	\$ 680.00	\$ 680.00 <i>350</i>
2	FRONT LH TYRE <i>2HP</i>	1	\$ 280.00	\$ 280.00 <i>X</i>
3	REAR LH WHEEL RIM <i>man</i>	1	\$ 680.00	\$ 680.00 <i>X</i>

550

TOTAL : \$ 1,640.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	<i>1000</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>1200 .</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TUFF COAT	\$ 150.00	<i>60</i>	
5	TO TRANSFER FRONT AND REAR DOOR FITTINGS	\$ 300.00	<i>200</i>	
6	TO DISMANTLE FRONT UNDERCARRIAGE	\$ 350.00	<i>X</i>	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80 .</i>	

TOTAL \$ 3,800.00

2570

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,818.68

TOTAL LABOUR COST: \$ 3,800.00

TOTAL REPAIR COST: \$ 10,618.68
10,980.55

total 7644.75

APPROVED DETAILS

11520.77

W/S: 6.1K.

SURVEYOR:

CONTACT:

FAX:

07 Days.

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____