

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 23 Jul 2020

Preliminary Advice

Insured Vehicle No	: SJP4131B		
TP Vehicle No	: SLU6641H	Accident Date	: 04/09/2019
Make	: TOYOTA COROLLA	Assignment Date	: 05/09/2019
Date of Inspection	: 23/04/2020	Est. Duration of Repair	: 3
Inspection At	: HUA HONG PTE LTD (SUNGEI KADUT) 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,783.23
Revised Amount	:S\$	1,844.55
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,844.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on wp