



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883
 Email: admin@nhtmotor.com Website: www.nhtmotor.com
 Tel: 6747 9241 Fax: 6741 7276
 UEN: 201718370K GST Reg No.: 201718370K

22-04-2020

Blk 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883

TP Somp
 Veron.

Accident date: 22/04/2020

Estimated repair cost for vehicle no: SKS7669U VOLKSWAGEN SCIROCCO 1.4I 11'

CHASSIS: WVWZZZ13ZCV013580

S/n	Qty	Items	U/price	Amount	
				\$1,930.75	1607 ✓
1	1	Rear Boot Lid <i>dentel</i>		\$215.60	+
2	2	Rear Boot Lid Hinge <i>2 set</i>	\$107.80	\$246.90	f
3	2	Rear Boot Lid Shock Absorber <i>2 set</i>	\$123.45	\$91.15	✓
4	1	Rear Boot Lid Emblem Logo <i>2</i>		\$97.35	✓
5	1	Rear Boot Lid Scirocco Logo <i>1 set</i>		\$69.55	✓
6	1	Rear Boot Lid Tsi Logo		\$850.00	f
7	1	Rear Boot Lid Top Spoiler (Special Nett) <i>new</i>		\$178.05	+
8	1	Rear Boot Lid Lock <i>new</i>		\$323.85	+
9	1	Rear Boot Lid Weatherstrip <i>new</i>		\$247.15	✓
10	1	Rear Boot Lid Inner Trim Board <i>at</i>		\$807.80	✓
11	1	Rear Boot Lid Windscreen <i>shattered</i>		\$80.00	60
12	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$850.00	+
13	1	Rear Boot Lid Reverse Camera <i>new</i>		\$84.00	✓
14	1	Rear Boot Lid Wiper Arm <i>at</i>		\$377.85	✓
15	1	Rear R/H Tail Lamp <i>could</i>		\$32.00	✓
16	4	Rear R/H Tail Lamp Clip <i>new</i>	\$8.00	\$1,275.05	1121 ✓
17	1	Rear Bumper <i>behind</i>		\$65.00	30
18	10	Rear Bumper Clip <i>new</i>	\$6.50	\$50.15	✓
19	1	Rear R/H Bumper Side Retainer <i>could</i>		\$67.45	+
20	1	Rear R/H Bumper Side Reflector <i>new</i>		\$106.00	+
21	1	Rear Bumper Inner Foam <i>new</i>		\$611.00	+
22	1	Rear Bumper Reinforcement <i>2 set</i>		\$450.00	f
23	1	Rear Bumper Reverse Sensor <i>1 set</i>		\$1,234.35	+
24	1	Rear End Panel <i>Repair</i>		\$161.05	+
25	1	Rear End Panel Top Garnish <i>2 set</i>		\$350.00	+
26	1	Rear End Panel Sealant <i>1 set</i>		\$1,773.00	+
27	1	Rear R/H Fender <i>Repair</i>		\$78.90	✓
28	1	Rear R/H Fender Air Duct <i>could</i>		\$209.45	+
29	1	Rear R/H Fender Cowling <i>new</i>			

30	10	Rear R/H Fender Cowling Clip	acc ~	\$6.50	\$65.00+
31	1	Rear R/H Fender Inner Trim Board	fac ~		\$296.65 +
32	8	Rear R/H Fender Inner Trim Board Clip		\$6.50	\$52.00 +
33	1 Set	Rear Rim	lit		\$2,500.00 (20/s)
34	1	Rear R/H Tyre	lit		\$550.00 (20/s)
35	1	Rear R/H Lower Arm			\$470.20 +
36	1	Rear R/H Knuckle Arm			\$774.80 +
37	1	Rear R/H Knuckle Arm Bearing			\$350.55 +
38	1	Rear R/H Shock Absorber			\$333.45 +
39	1	Rear R/H Trailing Arm			\$443.60 +

A75390

451670

Subtotal :- \$18,749.65

SN: 880

Labour charges

To remove & refit cushion & trim board	\$280.00	60
To remove & refit rear reverse sensor	\$100.00	50
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit rear R/H undercarriage	\$380.00	x
To check wheel alignment	\$150.00	80
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Towing fee	\$150.00	x
Panel beating	\$1,200.00	600
Spray painting	\$1,200.00	800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$3,880.00

Total:- \$22,629.65

5810

05 Days

Total: 7246.20
L/s: 5.8K
05 Days