



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

22-04-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Somp@

Veron.

Accident date: 22/04/2020

Estimated repair cost for vehicle no: SKS7669U VOLKSWAGEN SCIROCCO 1.4I 11'

CHASSIS: WVVZZZ13ZCV013580

| S/n | Qty | Items | U/price | Amount | 1607 |
|-----|-----|---|----------|-----------------------|------|
| | | | | \$1,930.75 | ✓ |
| 1 | 1 | Rear Boot Lid <i>dentel</i> | | \$215.60 | + |
| 2 | 2 | Rear Boot Lid Hinge <i>2 new</i> | \$107.80 | \$246.90 | + |
| 3 | 2 | Rear Boot Lid Shock Absorber <i>2 new</i> | \$123.45 | \$91.15 | ✓ |
| 4 | 1 | Rear Boot Lid Emblem Logo <i>2</i> | | \$97.35 | ✓ |
| 5 | 1 | Rear Boot Lid Scirocco Logo <i>2 new</i> | | \$69.55 | ✓ |
| 6 | 1 | Rear Boot Lid Tsi Logo | | \$850.00 | + |
| 7 | 1 | Rear Boot Lid Top Spoiler (Special Nett) <i>new</i> | | \$178.05 | + |
| 8 | 1 | Rear Boot Lid Lock <i>new</i> | | \$323.85 | + |
| 9 | 1 | Rear Boot Lid Weatherstrip <i>new</i> | | \$247.15 | ✓ |
| 10 | 1 | Rear Boot Lid Inner Trim Board <i>at</i> | | \$807.80 | ✓ |
| 11 | 1 | Rear Boot Lid Windscreen <i>shattered</i> | | \$80.00 | 60 |
| 12 | 1 | Rear Boot Lid Windscreen Seal <i>new</i> | | \$850.00 | + |
| 13 | 1 | Rear Boot Lid Reverse Camera <i>new</i> | | \$84.00 | ✓ |
| 14 | 1 | Rear Boot Lid Wiper Arm <i>at</i> | | \$377.85 | ✓ |
| 15 | 1 | Rear R/H Tail Lamp <i>could</i> | | \$8.00 | ✓ |
| 16 | 4 | Rear R/H Tail Lamp Clip <i>new</i> | \$8.00 | \$32.00 | ✓ |
| 17 | 1 | Rear Bumper <i>dentel</i> | | 1121 \$1,275.05 | ✓ |
| 18 | 10 | Rear Bumper Clip <i>new</i> | \$6.50 | \$65.00 | 30 |
| 19 | 1 | Rear R/H Bumper Side Retainer <i>could</i> | | \$50.15 | ✓ |
| 20 | 1 | Rear R/H Bumper Side Reflector <i>new</i> | | \$67.45 | + |
| 21 | 1 | Rear Bumper Inner Foam <i>new</i> | | \$106.00 | + |
| 22 | 1 | Rear Bumper Reinforcement <i>2 new</i> | | \$611.00 | + |
| 23 | 1 | Rear Bumper Reverse Sensor <i>2 new</i> | | \$450.00 | + |
| 24 | 1 | Rear End Panel <i>Repis</i> | | \$1,234.35 | + |
| 25 | 1 | Rear End Panel Top Garnish <i>2 new</i> | | \$161.05 | + |
| 26 | 1 | Rear End Panel Sealant <i>1 new</i> | | \$350.00 | + |
| 27 | 1 | Rear R/H Fender <i>Repis</i> | | \$1,773.00 | + |
| 28 | 1 | Rear R/H Fender Air Duct <i>could</i> | | \$78.90 | ✓ |
| 29 | 1 | Rear R/H Fender Cowling <i>new</i> | | \$209.45 | + |

| | | | | | | |
|----|-------|---------------------------------------|------|--------|------------|--------|
| 30 | 10 | Rear R/H Fender Cowling Clip | acc | \$6.50 | \$65.00 | + |
| 31 | 1 | Rear R/H Fender Inner Trim Board | free | | \$296.65 | + |
| 32 | 8 | Rear R/H Fender Inner Trim Board Clip | | \$6.50 | \$52.00 | + |
| 33 | 1 Set | Rear Rim | lit | | \$2,500.00 | 600/sn |
| 34 | 1 | Rear R/H Tyre | lit | | \$550.00 | 220/sn |
| 35 | 1 | Rear R/H Lower Arm | 2 | | \$470.20 | + |
| 36 | 1 | Rear R/H Knuckle Arm | | | \$774.80 | + |
| 37 | 1 | Rear R/H Knuckle Arm Bearing | lit | | \$350.55 | + |
| 38 | 1 | Rear R/H Shock Absorber | | | \$333.45 | + |
| 39 | 1 | Rear R/H Trailing Arm | | | \$443.60 | + |

4753.90

Subtotal :- \$18,749.65

451670

SN: 880

Labour charges

| | | |
|--|--|---------------------------|
| To remove & refit cushion & trim board | | \$280.00 60 |
| To remove & refit rear reverse sensor | | \$100.00 50 |
| To remove & refit rear windscreen | | \$120.00 ✓ |
| Gum | | \$50.00 ✓ |
| To remove & refit rear R/H undercarriage | | \$380.00 x |
| To check wheel alignment | | \$150.00 80 |
| To check wiring | | \$100.00 30 |
| Tuff kote | | \$150.00 60 |
| Towing fee | | \$150.00 x |
| Panel beating | | \$1,200.00 600 |
| Spray painting | | \$1,200.00 800 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1850

Subtotal :- \$3,880.00

Total:- \$22,629.65

58K

Total: 7246.20

W/S: 5.8K

05 Days

05 Days