



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

22-04-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.

Cerilia.

V F 3 L P H X Y W G S 168 582

Accident date: 22/04/2020

Estimated repair cost for vehicle no: SLH22875 PEUGEOT 308 '16

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Regis torn</i>		\$1,218.00 ✓ 785
2	10	Front Bumper Clip <i>New</i>	\$6.50	\$65.00 ✓
3	1	Front Bumper Sensor <i>New</i>		\$326.00 ✓
4	1	Front L/H Bumper Side Retainer <i>New</i>		\$91.00 ✓
5	1	Front L/H Head Lamp <i>lit</i>		\$2,165.00 ✓ 1385
6	1	Front L/H Fender <i>Detol.</i>		\$562.00 ✓
7	1	Front L/H Fender Cowling <i>3/4</i>		\$184.00 ✓
8	10	Front L/H Fender Cowling Clip <i>3/4</i>	\$6.50	\$65.00 ✓
9	1	Front L/H Door <i>Detol.</i>		\$1,652.00 ✓ 1095
10	2	Front L/H Door Hinge <i>New</i>	\$92.00	\$184.00 ✓
11	1	Front L/H Door Lock <i>New</i>		\$362.00 ✓
12	1	Front L/H Door Handle <i>Not fit</i>		\$356.00 ✓
13	1	Front L/H Door Weatherstrip <i>New</i>		\$282.00 ✓
14	1	Front L/H Door Chrome Moulding Top <i>cut</i>		\$206.00 ✓
15	1	Front L/H Door Chrome Moulding Lower <i>lit</i>		\$224.00 ✓
16	1	Front L/H Door Inner Trim Board <i>New</i>		\$642.00 ✓
17	1	Front L/H Door Glass <i>lit</i>		\$686.00 ✓
18	1	Front L/H Side Mirror Assy <i>can't</i>		\$955.00 ✓
19	1	Front L/H Rim <i>lit</i>		\$1,578.00 ✓ 62/sv
20	1	Front L/H Tyre <i>New</i>		\$550.00 ✓
21	1	Front L/H Lower Arm <i>Best</i>		\$392.00 ✓
22	1	Front L/H Knuckle Arm <i>Best</i>		\$565.00 ✓
23	1	Front L/H Knuckle Arm Bearing <i>New</i>		\$356.00 ✓
24	1	Front L/H Shock Absorber <i>Best</i>		\$405.00 ✓
25	1	Front L/H Drive Shaft <i>Not New</i>		\$1,876.00 ✓
26	1	Front Steering Rack <i>Best</i>		\$3,562.00 ✓ 2150
27	1	Rear Bumper <i>Regis</i>		\$1,045.00 ✓
28	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00 ✓
29	2	Rear Bumper Reverse Sensor <i>New</i>	\$326.00	\$652.00 ✓

30	1	Rear L/H Bumper Side Retainer	New		\$91.00	✓
31	1	Rear L/H Tail Lamp	Lot		\$356.00	✓
32	1	Rear L/H Fender	Pay		\$1,659.00	✓
33	1	Rear L/H Fender Cowling	New		\$229.00	✓
34	10	Rear L/H Fender Cowling Clip	New	\$6.50	\$65.00	✓
35	1	Rear L/H Door	Pay		\$1,652.00	✓
36	2	Rear L/H Door Hinge		\$92.00	\$184.00	✓
37	1	Rear L/H Door Lock			\$362.00	✓
38	1	Rear L/H Door Handle			\$356.00	✓
39	1	Rear L/H Door Weatherstrip			\$282.00	✓
40	1	Rear L/H Door Chrome Moulding Top	NI		\$206.00	✓
41	1	Rear L/H Door Chrome Moulding Lower	NI		\$224.00	✓
42	1	Rear L/H Door Inner Trim Board			\$642.00	✓
43	1	Rear L/H Door Quarter Glass Assy			\$605.00	✓
44	1	Rear L/H Rim	Lot		\$1,578.00	✓
45	1	Rear L/H Tyre	New		\$550.00	✓
46	1	Rear L/H Shock Absorber	New		\$412.00	✓
47	1	Rear L/H Axle Bearing	New		\$376.00	✓
48	1	Rear L/H Axle	New		\$2,680.00	✓

Subtotal :- \$33,780.00

10404

9363.60

S N 1200

Labour charges

To remove & refit front reverse sensor	\$100.00 50
To remove & refit rear reverse sensor	\$100.00 +
To remove & refit front L/H door & components	\$280.00 80
To remove & refit rear L/H door & components	\$280.00 x
To remove & refit front undercarriage, drive shaft & steering rack	\$450.00 300
To remove & refit rear undercarriage, axle & bearing	\$450.00 80
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 60
Tuff kote	\$150.00 60
Towing fee	\$150.00 +
Panel beating	\$2,200.00 800
Spray painting	\$2,000.00 1200

Subtotal :- \$6,410.00

Total:- \$40,190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
h/s 23/04/20

0.7 Days

Total 13273.60

h/s 10.6k

10.6k

0.7 Days