



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20005357/Eea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-06-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3278K	Veh. Inspected	SMP 943R
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001958MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	23/04/2020

2. Vehicle Particulars & Condition

Make & Model	MINI COOPER S	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMWXS720002E45230	Colour	WHITE
Odometer	33072	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R17	FIRELLI	5 mm
L/H Front Tyre	205/45 R17	FIRELLI	5 mm
R/H Rear Tyre	205/45 R17	FIRELLI	5 mm
L/H Rear Tyre	205/45 R17	FIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/04/2020	Inspection Date	04/05/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**