



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 28/4/2020
 Vehicle: SMP943R
 Make / Model: MINI COOPER
 Chassis: WMWXS720002E45230

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	LH FRONT DOOR <i>X R</i>		\$ 1,658.65	\$ 1,658.65
2	LH REAR DOOR <i>/ OO</i>		\$ 1,358.65	\$ 1,358.65
3	LH ROCKER PANEL GARNISH <i>/ CM</i>		\$ 983.10	\$ 983.10
4	LH REAR WHEEL ARCH GARNISH <i>X NN</i>		\$ 241.60	\$ 241.60
				\$ 4,242.00
			Less 10%	\$ 424.20
			Total	\$ 3,817.80
S/Nett items:				
1	MISCELLANEOUS <i>APC</i>	1	\$ 150.00	\$ 150.00
				\$ 150.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND TRANSFER BOTH LH DOORS FITTING	1	\$ 300.00	\$ 300.00
3	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 200.00	\$ 200.00
4	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,400.00
			Parts Replacement Amount	\$ 3,967.80
			Total Amount for Labour	\$ 2,400.00
			Total Amount	\$ 6,367.80

X
 1136.19
 786.40
 X
 1922.59
 -10%
 1730.33
 /30
 30
 80
 X
 30
 30
 500
 400
 1070

Steve (LKX)

ML PL

P-1730-33

3 days

N-30

L/S

L-1070

M PL SVJ

2830.33

4/5/19, 2.29pm

L/S-2264.26

= 2250

KK Auto Consultants hence notify
 the Repairer of the following:
 To resurvey before/after spray painting
 To display damaged part(s) during resurvey
 Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company