



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 28/4/2020
 Vehicle: SMP943R
 Make / Model: MINI COOPER
 Chassis: WMWXS720002E45230

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	LH FRONT DOOR <i>x R</i>		\$ 1,658.65	\$ 1,658.65
2	LH REAR DOOR <i>/ 00</i>		\$ 1,358.65	\$ 1,358.65
3	LH ROCKER PANEL GARNISH <i>/ (MT)</i>		\$ 983.10	\$ 983.10
4	LH REAR WHEEL ARCH GARNISH <i>X</i>		\$ 241.60	\$ 241.60
				\$ 4,242.00
			Less 10%	\$ 424.20
			Total	\$ 3,817.80
S/Nett items:				
1	MISCELLANEOUS	1	\$ 150.00	\$ 150.00 <i>/30</i>
				\$ 150.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00 <i>30</i>
2	REMOVE AND TRANSFER BOTH LH DOORS FITTING	1	\$ 300.00	\$ 300.00 <i>80</i>
3	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 200.00	\$ 200.00 <i>X</i>
4	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00 <i>30</i>
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00 <i>30</i>
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 <i>500</i>
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 <i>400</i>
				\$ 2,400.00
			Parts Replacement Amount	\$ 3,967.80
			Total Amount for Labour	\$ 2,400.00
			Total Amount	\$ 6,367.80

Steve (LKK) ML PL

3 days

L/S

My AC SVJ

4/5/20, 2.29pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: