

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 55063**  
Date Estimated : **20/04/2020**  
Prepared By : **Chua Kee Sin**

### - ESTIMATE REPAIR FOR -

**Ang Sui Oon**  
**30 Shangri-La Walk**

**Singapore 568207**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SFG36P</b>	<b>WBA7E02050G245393</b>	<b>08/12/2017</b>	<b>730Li</b>	<b>46420</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including make good the bootlid and remove attachments to facilitate repairs.	1,700.00		1,700.00
To respray rear bumper and bootlid.	1,868.00		1,868.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	216.00		216.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,746.65	1.00		1,746.65
EMBLEM GROMMET	0.85	2.00		1.70
LETTERING 730LI	64.45	1.00		64.45
REAR PLAQUE 82MM	71.60	1.00		71.60

#### # SUPPLEMENTARY ITEMS

Total Labour :	4,014.00
Total Parts :	1,884.40
Total Labour & Parts :	5,898.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,898.40
GST @7%:	412.89
Grand Total :	6,311.29