

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Irene Tay Hui Ping	Date:	09 Jun 2020

**Preliminary Advice**

Insured Vehicle No	:	GBG9180T		
TP Vehicle No	:	SFG36P	Accident Date	: 20/04/2020
Make	:	BMW 730LI	Assignment Date	: 23/04/2020
Date of Inspection	:	08/06/2020	Est. Duration of Repair	: 5.00
Inspection At	:	PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	\$ 9,281.75
Revised Amount	:	\$ 1,884.40
Check Items (Estimated)	:	\$ 2,528.10
Total	:	\$ 4,412.50
Lump Sum Repair		:

&lt;/div