

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

Due 2/21
8/6/2020
arr
Emergency Repair



GST REG. NO : M2 - 0020081 - X

20 APR 2020

E S T I M A T E

Estimate No. : b1 55063
 Date Estimated : 20/04/2020
 Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ang Sui Oon
 30 Shangri-La Walk

Singapore 568207

- ACCOUNT - 40000

Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG36P	WBA7E02050G245393	08/12/2017	730Li	0

DESCRIPTION

Replace rear bumper include repair rear boot lid and remove attachment etc

1700 2,125.00

Spray painting rear bumper and rear boot lid

1868 2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

216 271.00

Sundries.

rec ✓ ? 80.00

Total Labour 1: **4,729.00**

DESCRIPTION

REAR BUMPER CARRIER
 REAR LH MOULDING ROCKER PANEL
 REAR RH MOULDING ROCKER PANEL
 REAR BUMPER CENTRE GUARD
 REAR BUMPER GUARD
 REAR BUMPER COVER
 Protection f
 REAR BUMPER TRIM PRIMED
 REAR BUMPER PANEL PRIMED (PDC/PMA)
 LEFT PROTECT
 RIGHT PROTEC
 EMBLEM GROMMET
 LETTERING 730LI
 REAR PLAQUE 82MM
 ULTRASONIC SENSOR BLACK
 DECOUPLING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	976.10	? 976.10
1	55.15	? 55.15
1	55.15	? 55.15
1	83.85	? 83.85
1	110.25	x 110.25
1	110.00	x 110.00
2	8.95	? 17.90
1	216.45	? 216.45
1	1,746.65	de ✓ 1,746.65
1	11.65	? 11.65
1	11.65	? 11.65
2	0.85	rec ✓ 1.70
1	64.45	rec ✓ 64.45
1	71.60	rec ✓ 71.60
4	249.95	X ? 999.80
4	5.10	nn ? 20.40

Total Parts : **4,552.75**

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 55063	Page No. :	2 of 5
Date Estimated	: 20/04/2020		
Prepared By	: Chua Kee Sin		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG36P	WBA7E02050G245393	08/12/2017	730Li	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>8/6/20</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495719</u>	Authorised <u>Yes/No</u>
Authorised Date <u>WP'</u>	Time <u>1110</u>
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>RML</u> Yes / No	
Surveyor's E-mail <u>tanjiah@lkkhards.com</u>	
No of Working Days Recommend <u>05 days</u>	

Labour 1	:	4,729.00
Parts	:	4,552.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	649.72
Grand Total	:	