

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG20005359/R1sf3e2		
4 SHENTON WAY #21-01,SGX CENTRESINGAPORE 068807			Date: 06-05-2020 Code: MSG		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SGK 45E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From	ONG SHU XIANG	Assign Date	23/04/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA MR2 T/B ROOF	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	1991	
	Chassis No.	JT163SW2000019963	Colour	BLACK	
	Odometer	439196	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/40 R17	FALKEN	6 mm	
	L/H Front Tyre	215/40 R17	FALKEN	6 mm	
	R/H Rear Tyre	215/40 R17	FALKEN	6 mm	
	L/H Rear Tyre	215/40 R17	FALKEN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/04/2020	Inspection Date	23/04/2020	
	Survey held at	eld at KOLORWERX AUTOSHOP PTE LTD			
		48 TOH GUAN ROAD EAST #04-116 ENTERPRISE HUB SINGAPORE 608586			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				