



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104317
INV Date 17/06/2021
Reference CC4/LPC20005361/Kea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 6166C
Insured Veh. XD 4524Z
Claim No. 20/20/20/VC05/023317
Policy No. Z20VC05004347
Accident Date 15/04/2020
Inspection Date 27/04/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CC4/LPC20005361/Kea3q2 Date: 17/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 4524Z	Veh. Inspected	SJR 6166C
Policy No.	Z20VC05004347	Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023317	Excess (\$)	0.00
Assign From	GERALD	Assign Date	23/04/2020
2. Vehicle Particulars & Condition			
Make & Model	LEXUS IS300 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTHBA1D2905079113	Colour	METALLIC BLACK
Odometer	53798 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	YOKOHAMA	4 mm
L/H Front Tyre	235/40 R18	YOKOHAMA	4 mm
R/H Rear Tyre	235/40 R18	MICHELIN	7 mm
L/H Rear Tyre	235/40 R18	MICHELIN	7 mm
4. Description of Damages			
NO DAMAGED FOUND AT TIME OF INSPECTION.			
5. General Information			
Accident Date	15/04/2020	Inspection Date	27/04/2020
Survey held at	LIM MOTOR PTE LTD 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 6166C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LHF RIM	* CHECK	1,289.00	-
1	LHF WHEEL BEARING HUB	* CHECK	698.00	-
1	LHF KNUCKLE ARM	* CHECK	1,231.00	-
1	LHF LOWER ARM	* CHECK	491.00	-
1	LHF UPPER ARM	* CHECK	505.00	-
1	LHF LOWER BALLJOINT	* CHECK	140.00	-
1	LHF STABILIZER LINK	SERVICEABLE	134.00	-
1	LHF SPRING STRUT	* CHECK	1,067.00	-
	LESS 10% DISCOUNT		-	-
			5,555.00	-
<u>LABOUR</u>				
	RENEW LHF RIM .	* CHECK	30.00	-
	RENEW LHF UNDERCARRIAGES.	* CHECK	280.00	-
	WHEEL ALIGNMENT.		100.00	60.00
	CONDUCT SPRAY PAINTING ON AFFECTED PANELS.	NOT NECESSARY	500.00	-
	COATING (FRONT BUMPER).	NOT NECESSARY	180.00	-
			1,090.00	60.00
GRAND TOTAL			6,645.00	60.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$5,188.90 NETT)				60.00

Report Ref No. CC4/LPC20005361/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 6166C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

